



**FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
LARGE AIRCRAFT**

BIWEEKLY 2008-09

This electronic copy may be printed and used in lieu of the FAA biweekly paper copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Delegation and Airworthiness Programs Branch, AIR-140
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2008-01

2007-26-07		Boeing	747-200B, 747-300, 747-400, 747-400D, and 747-400F
2007-26-16		Cessna	680
2007-26-20		Pratt & Whitney	Engine: PW4164, PW4168, and PW4168A

Biweekly 2008-02

90-25-05R1	R 90-25-05	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2004-07-22R1	R 2004-07-22	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2007-23-12	COR	Boeing	707-100 long body, -200, -100B long body, and -100B short body, 707-300, -300B, -300C, and -400, 720 and 720B
2007-26-11		Intertechnique Zodiac Aircraft Systems	Appliance: Oxygen reserve cylinders
2007-26-14	S 2003-06-04	Airbus	A300 airplanes; and all Model A300 B4-601, B4-603, B4-620, B4-622, B4-605R, B4-622R, F4-605R, F4-622R, and C4-605R Variant F
2007-26-17	S 2006-10-04	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2007-26-18		BAE Systems	BAe 146-100A, -200A, and -300A, Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A
2007-26-19	S 2004-26-10	Rolls-Royce Deutschland Ltd	Engine: Tay 611-8, Tay 620-15, Tay 650-15, and Tay 651-54, Tay 611-8C
2007-26-21		EMBRAER	EMB-120, -120ER, -120FC, -120QC, and -120RT
2008-01-02		Viking Air Limited	(Caribou) DHC-4 and (Caribou) DHC-4A
2008-01-03		Learjet	45
2008-01-04	S 2007-17-07	Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-01-05	S 2004-15-16	Airbus	A310
2008-02-01		EMBRAER	EMB 135BJ
2008-02-02		EMBRAER	ERJ 170-100 LR, -100 STD, -100 SE, -100 SU, -200 LR, -200 STD, and -200 SU, ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW

Biweekly 2008-03

2008-02-05		Boeing	777-200 and -300
2008-02-07		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-02-08		McDonnell Douglas	717-200
2008-02-12		McDonnell Douglas	717-200
2008-02-13		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F
2008-02-14		Boeing	747-400, -400D, and -400F, 757-200, -200CB, and -200PF, 757-300, 767-200, -300, and -300F, 767-400ER
2008-02-15		Airbus	A319 and A320
2008-02-16		Boeing	767-200 and 767-300
2008-02-17	S 99-18-20	General Electric Company	CF6-50, -80A1/A3, and -80C2A
2008-02-19		Honeywell International Inc	Engine: TFE731-2C, -3B, -3BR, -3C, -3CR, -3D, -3DR, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, -40AR, -40R, and -60
2008-03-03		Embraer	EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2008-03-04		Airbus	A300 B4-600, A300 B4-600R, A300 C4-600R, and A300 F4-600R

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2008-04			
90-25-05 R1	COR	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2004-07-22 R1	COR	Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2006-11-05 R2		Rolls Royce	Engine: RB211-22B series, RB211-524B, -524C2, -524D4, -524G2, -524G3, and -524H series, and RB211-535C and -535E
2008-01-02	COR	Viking Air Limited	(Caribou) DHC-4 and (Caribou) DHC-4A
2008-03-05		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2008-03-08		SAAB Aircraft AB	SAAB 2000
2008-03-09		CFM International, S.A	Engine: CFM56-7B18, -7B20, -7B22, -7B24, -7B26, -7B27, -7B22/B1, -7B24/B1, -7B26/B1, -7B27/B1, -7B22/B2, -7B26/B2, -7B27/B3
2008-03-12	S 2006-07-25	McDonnell Douglas	See AD
2008-03-13		ATR-GIE Avions de Transport Régional	ATR42-500
2008-03-17		SaaB Aircraft AB	SAAB SF340A and SAAB 340B
2008-03-18		SaaB Aircraft AB	SAAB SF340A and Model SAAB 340B
2008-03-19		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-03-20		Boeing	737-300, -400, and -500
2008-03-21		Fokker Services B.V	F.27 Mark 050
2008-04-01		Airbus	A300, A310, and A300-600
2008-04-02		Bombardier, Inc.	DHC-8-400, DHC-8-401, and DHC-8-402
2008-04-04		Bombardier, Inc.	DHC-8-400, DHC-8-401, and DHC-8-402
Biweekly 2008-05			
2008-04-06		Boeing	707-100 long body, -200, -100B long body, and -100B short body, 707-300, -300B, -300C, -400, 720 and 720B
2008-04-07		Saab Aircraft AB	SF340A and SAAB 340B
2008-04-08		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-04-10		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F
2008-04-11		Boeing	707-100 long body, -200, -100B long body, -100B short body; Model 707-300, -300B, -300C, -400, 720 and 720B
2008-04-12	S 2004-23-14	Boeing	767-200, -300, -300F, and -400ER
2008-04-13		ATR-GIE	ATR42-200, -300, -320, and -500, ATR72-101, -201, -102, -202, -211, -212, and -212A
2008-04-14	S 2000-12-15	Dassault Aviation	Falcon 2000, Falcon 2000EX, Mystere-Falcon 900, Falcon 900EX, Fan Jet Falcon, Mystere-Falcon 50, Mystere-Falcon 20, Mystere-Falcon 200, and Falcon 10
2008-04-16		BAE Systems	BAe 146 and Model Avro 146-RJ
2008-04-17		Bombardier, Inc.	DHC-8-102, DHC-8-103, DHC-8-106, DHC-8-201, DHC-8-202, DHC-8-301, DHC-8-311, and DHC-8-315 and DHC-8-400
2008-04-18		Embraer	EMB-120, -120ER, -120FC, -120QC, and -120RT
2008-04-19		ATR-GIE	ATR42-200, -300, -320, and -500 airplanes; and all ATR Model ATR72-101, -201, -102, -202, -211, -212, and -212A
2008-04-20		Airbus	A319, A320, and A321
2008-04-21		Boeing	737-300, -400, and -500
2008-04-22		Fokker Services B.V	F.28 Mark 0070 and 0100
2008-05-01		General Electric Company	Engine: CF34-8C1/-8C5/-8C5B1/-8E5/-8E5A1

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
Biweekly 2008-06			
2007-25-12	COR	Airbus	A318, A319, A320, and A321
2008-05-02	S 2005-25-04	Embraer	EMB-135BJ, -135ER, -135KE, -135KL, -135LR, -145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP
2008-05-03		Boeing	747-100, -100B, -100B SUD, -200B, -200C, -200F, -300, 747SP, and 747SR
2008-05-04		Airbus	A330-201, -202, -203, -223, -243, -301, -321, -322, -323, -341, -342, and -343 airplanes; A340-200 and -300
2008-05-05		Boeing	737-600, 737-700, 737-700C, 737-800, and 737-900
2008-05-06		Boeing	737-100, -200, -300, -400, and -500
2008-05-07		Dassault Aviation	Fan Jet Falcon, Fan Jet Falcon series C, D, E, F, and G airplanes; Model Mystere-Falcon 200 airplanes; and Model Mystere-Falcon 20-C5, 20-D5, 20-E5, and 20-F5
2008-05-08		Dassault Aviation	Mystere-Falcon 50
2008-05-10	S 2007-16-13	Boeing	757-200, -200PF, and -200CB
2008-05-12	S 2006-04-06	Airbus	A318-111, -112, -121, and -122, A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111 airplanes; Model A320-211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, -131, -211, -212, -213, -231, and -232
2008-05-13	S 2006-17-14	Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 and 440)
2008-05-18		Fokker Services B.V	F27 Mark 050 airplanes, all serial numbers; and Fokker F27 Mark 200, 300, 400, 500, 600, and 700
2008-06-01		Bombardier, Inc.	CL-600-2C10 (Regional Jet Series 700, 701, & 702), Model CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900)
2008-06-02		Bombardier, Inc	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-06-03		Boeing	737-600, -700, -700C, -800 and -900 series airplanes; and Boeing Model 757-200, -200PF, -200CB, and -300
2008-06-04		Airbus	A300 and A300-600
2008-06-05	S 2004-03-24	Airbus	A330-200, A330-300, A340-200, and A340-300
2008-06-06		Boeing	767-200, -300, -300F, and -400ER
2008-06-07	S 2005-23-10	Airbus	A330-200, A330-300, A340-200, and A340-300
2008-06-08		BAE Systems	BAe 146-100A, -200A, and -300A
2008-06-09		Boeing	737-200
2008-06-10		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 440)
2008-06-11		Saab AB	SAAB SF340A and SAAB 340B (including Variant 340B
2008-06-13	S 2007-05-01	Construcciones Aeronauticas, S.A	C-212
2008-06-14		Boeing	757-200, -200PF, and -200CB
2008-06-51	E	Lycoming Engines	Engine: IO, (L)IO, TIO, (L)TIO, AEIO, AIO, IGO, IVO, and HIO series reciprocating engines, Teledyne Continental Motors (TCM) TSIO-360-RB reciprocating engines, and Superior Air Parts, Inc. IO-360

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency

Biweekly 2008-07

2008-06-18		Airbus	A300 series airplanes and Model A300-600
2008-06-19		Honeywell International Inc.	Engine: ATF3-6-4C, ATF3-6A-3C, and ATF3-6A-4C turbofan
2008-06-20		Fokker Services B.V	F.28 Mark 0070 and 0100 and Model F.28 Mark 1000, 2000, 3000, and 4000
2008-06-21		McDonnell Douglas	DC-10-10 and DC-10-10F airplanes, Model DC-10-15 airplanes, Model DC-10-30 and DC-10-30F (KC-10A and KDC-10) airplanes, Model DC-10-40 and DC-10-40F airplanes, Model MD-10-10F and MD-10-30F airplanes, and Model MD-11 and MD-11F
2008-06-23		McDonnell Douglas	DC-8-55, DC-8F-54, DC-8F-55, DC-8-61, DC-8-62, DC-8-63, DC-8-61F, DC-8-62F, DC-8-63F, DC-8-71, DC-8-72, DC-8-73, DC-8-71F, DC-8-72F, and DC-8-73F
2008-06-24		Boeing	737-300, -400, and -500
2008-06-25		Airbus	A330 and A340, A330-300
2008-06-26		Airbus	A330-200, A330-300, A340-200, and A340-300
2008-06-27		Goodrich	Appliance: Goodrich evacuation systems
2008-06-29		Boeing	737-300, -400, and -500
2008-07-03		Saab Aircraft AB	SF340A (SAAB/SF340A) and SAAB 340B
2008-07-07		DTAA, Inc.	Appliance: Auxiliary fuel tank system
2008-07-09		Southeast Aero-Tek, Inc	Appliance: Auxiliary fuel tank

Biweekly 2008-08

No Large Aircraft ADs were issued during Biweekly 2008-08.

Biweekly 2008-09

2006-12-10 R1		Boeing	747-400
2008-06-07	COR	Airbus	A330-200, A330-300, A340-200, and A340-300
2008-08-01	S 2003-15-01, 2006-17-10, 2006-15-13	McCauley Propeller System	Propeller: B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0
2008-08-02		Boeing	727, 727C, 727-100, 727-100C, 727-200, and 727-200F
2008-08-04	S 2006-11-04	Airbus	A318, A319, A320, and A321
2008-08-05		Fokker Services B.V.	F.27 Mark 050 and F.28 Mark 0100
2008-08-06	S 2005-04-07	Bombardier, Inc	CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, & CL-604)
2008-08-07		Saab Aircraft AB	SF340A (SAAB/SF340A), 340B
2008-08-08		Boeing	757-200, -200CB, -200PF, and -300
2008-08-09		Bombardier, Inc.	CL-600-2B19 (Regional Jet Series 100 & 400)
2008-08-10		Boeing	737-100, -200, -200C, -300, -400, and -500
2008-08-12		Boeing	757-200, -200PF, -200CB, and -300
2008-08-13		Airbus	A310-304, -322, -324, and -325, A300 Model B4-601, B4-603, B4-605R, B4-620, B4-622, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes (commonly called Model A300-600 series airplanes)
2008-08-14	S 2006-06-51	Precision Airmotive LLC	Engine: IO, (L)IO, TIO, (L)TIO, AEIO, AIO, IGO, IVO, and HIO series reciprocating engines, Teledyne Continental Motors (TCM) TSIO-360-RB reciprocating engines, and Superior Air Parts, Inc. IO-360 series reciprocating engines with certain Precision Airmotive LLC RSA-5 and RSA-10 series fuel injection servos
2008-08-18		Fokker Services B.V	F.28 Mark 0070 and Mark 0100
2008-08-19		Gulfstream Aerospace LP	G150
2008-08-20		Dassault Aviation	Falcon 2000
2008-08-21	S 2006-11-15	Embraer	ERJ 170-100 LR, -100 SE, -100 STD, -100 SU, -200 LR, -200 STD, and -200 SU airplanes; and Model ERJ 190-100 IGW, -100 LR, -100 STD, -200 IGW, -200 LR, and -200 STD
2008-08-22		Boeing	737-600, -700, -700C, -800, and -900
2008-08-23		Boeing	737-200C
2008-08-24		Boeing	737-600, -700, -700C, -800, and -900
2008-08-25		Boeing	747-400F, 747-400

LARGE AIRCRAFT

AD No.	Information	Manufacturer	Applicability
Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; FR - Final Rule of Emergency			
2008-08-26		Boeing	767-200, -300, -300F, and -400ER
2008-09-04		McDonnell Douglas	DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, and DC-8-43 airplanes; Model DC-8-51, DC-8-52, DC-8-53, and DC-8-55 airplanes; Model DC-8F-54 and DC-8F-55 airplanes; Model DC-8-61, DC-8-62, and DC-8-63 airplanes; Model DC-8-61F, DC-8-62F, and DC-8-63F airplanes; Model DC-8-71, DC-8-72, and DC-8-73 airplanes; and Model DC-8-71F, DC-8-72F, and DC-8-73F
2008-09-05		Boeing	747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP
2008-09-07		Boeing	757-200, -200PF, -200CB, and -300 series airplanes, and Model 767-200, 767-300, and 767-300F



2006-12-10 R1 Boeing: Amendment 39-15485. Docket No. FAA-2008-0410; Directorate Identifier 2007-NM-362-AD.

Effective Date

- (a) This AD becomes effective May 7, 2008.

Affected ADs

- (b) This AD revises AD 2006-12-10.

Applicability

- (c) This AD applies to Boeing Model 747-400 series airplanes, certificated in any category, as identified in Boeing Special Attention Service Bulletin 747-35-2114, Revision 1, dated June 7, 2007.

Unsafe Condition

(d) This AD results from a report indicating that certain oxygen cylinder supports may not have been properly heat-treated. We are issuing this AD to prevent failure of the oxygen cylinder support under the most critical flight load conditions, which could cause the oxygen cylinder to come loose and leak oxygen. Leakage of oxygen could result in oxygen being unavailable for the flightcrew or could result in a fire hazard in the vicinity of the leakage.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Action

(f) At the compliance time specified in paragraph (f)(1) or (f)(2) of this AD as applicable, except as provided by paragraph (g) of this AD: Inspect the support bracket of the crew oxygen cylinder installation to determine the manufacturing date marked on the support, and do the corrective action as applicable, by doing all of the actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002; or Revision 1, dated June 7, 2007. Corrective action, if applicable, must be done before further flight after the inspection. After the effective date of this AD only Revision 1 of the service bulletin may be used.

(1) For airplanes identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: Within 18 months after July 17, 2006 (the effective date of AD 2006-12-10).

(2) For airplanes not identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: Within 18 months after the effective date of this AD.

(g) If the configuration of the crew oxygen cylinder installation is changed from a one-cylinder to a two-cylinder configuration: Do the actions required by paragraph (f) of this AD before further

flight after the change in configuration, or at the applicable time specified in paragraph (g)(1) or (g)(2), whichever is later.

(1) For airplanes identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: Within 18 months after July 17, 2006.

(2) For airplanes not identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: Within 18 months after the effective date of this AD.

Parts Installation

(h) At the time specified in paragraph (h)(1) or (h)(2) of this AD as applicable, no person may install an oxygen cylinder support bracket having part number 65B68258-2 and having a manufacturing date between 10/01/98 and 03/09/01 inclusive (meaning, a manufacturing date of 10/01/98 or later and 03/09/01 or earlier).

(1) For airplanes identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: As of July 17, 2006.

(2) For airplanes not identified in Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002: As of the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006-12-10, are approved as AMOCs for the corresponding provisions of paragraph (f) and (g) of this AD.

Material Incorporated by Reference

(j) You must use Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002; or Boeing Special Attention Service Bulletin 747-35-2114, Revision 1, dated June 7, 2007; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Special Attention Service Bulletin 747-35-2114, Revision 1, dated June 7, 2007, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On July 17, 2006 (71 FR 33604, June 12, 2006), the Director of the Federal Register approved the incorporation by reference of Boeing Special Attention Service Bulletin 747-35-2114, dated December 19, 2002.

(3) Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 14, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8531 Filed 4-21-08; 8:45 am]



CORRECTION: [*Federal Register*: April 15, 2008 (Volume 73, Number 73)]; Page 20367;
www.access.gpo.gov/su_docs/aces/aces140.html]

2008-06-07 Airbus: Amendment 39-15419. Docket No. FAA-2007-0230; Directorate Identifier 2007-NM-043-AD.

Effective Date

- (a) This AD becomes effective April 16, 2008.

Affected ADs

- (b) This AD supersedes AD 2005-23-10.

Applicability

- (c) This AD applies to the airplanes identified in Table 1 of this AD, certificated in any category.

Table 1 – Applicability

Airbus Model –	Excluding those airplanes on which any of the following –	Has been installed –
A330-200, A330-300, A340-200, and A340-300 series airplanes	Airbus modification 54833	In production
	Airbus Service Bulletin A330-27-3136, Revision 01, dated July 19, 2006	In service
	Airbus Service Bulletin A340-27-4135, dated January 12, 2006	In service

Unsafe Condition

(d) This AD results from reports of failed elevator servo controls due to broken guides. We are proposing this AD to prevent failure of the elevator servo controls during certain phases of takeoff, which could result in an unannounced loss of elevator control and consequent reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Requirements of AD 2005-23-10:

Service Information

(f) The term "AOT," as used in paragraphs (g) through (i) of this AD, means section 4.2. "Description" of the following service information, as applicable:

- (1) For Model A330-200 and -300 series airplanes: Airbus All Operators Telex A330-27A3138, Revision 01, dated October 3, 2005; and
- (2) For Model A340-200 and -300 series airplanes: Airbus All Operators Telex A340-27A4137, Revision 01, dated October 3, 2005.

Initial and Repetitive Elevator Servo-Loop Tests

(g) Within 200 flight hours after November 29, 2005 (the effective date of AD 2005-23-10): Test the elevator servo-loops, in accordance with the AOT, except as provided by paragraph (j) of this AD. If the test of the elevator servo-loops passes, repeat the test at intervals not to exceed 140 flight hours or 8 days, whichever occurs first.

Failed Tests

(h) If any test of the elevator servo-loops required by paragraph (g) of this AD fails: Before further flight, troubleshoot the cause of the test failure, and do the applicable corrective actions; in accordance with the AOT, except as provided by paragraph (j) of this AD. Thereafter, repeat the test at the times specified in paragraph (g) of this AD.

Reporting Requirement

(i) Following each test required by paragraph (g) of this AD, submit a report of the findings of only failed elevator servo-loop tests to Airbus Customer Services, Engineering and Technical Support, Attention: Mr. J. Laurent, SEE53, fax +33/(0)5.61.93.44.25; at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the description of the failure experienced during the test, the identified cause of the failure, and the number of flight hours and flight cycles on the airplane. Under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

- (1) If the test was done after November 29, 2005: Submit the report within 10 days after the test.
- (2) If the test was done prior to November 29, 2005: Submit the report within 10 days after November 29, 2005.

New Requirements of This AD

New Service Information for Testing

(j) As of the effective date of this AD, do the actions required by paragraphs (g) and (h) of this AD in accordance with the Accomplishment Instructions of the following service bulletins, as applicable.

- (1) For Model A330-200 and -300 series airplanes: Airbus Service Bulletin A330-27-3138, Revision 02, excluding Appendix 01, dated May 30, 2006; and
- (2) For Model A340-200 and -300 series airplanes: Airbus Service Bulletin A340-27-4137, Revision 02, excluding Appendix 01, dated May 30, 2006.

Terminating Actions

(k) Within 17 months after the effective date of this AD, modify the four elevator servo controls in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-27-3136, Revision 01, dated July 19, 2006 (for Model A330-200 and -300 series airplanes); or Airbus Service Bulletin A340-27-4135, dated January 12, 2006 (for Model A340-200 and -300 series airplanes); as applicable.

Note 1: Airbus Service Bulletins A330-27-3136 and A340-27-4135 refer to Goodrich Actuation Systems Service Bulletin SC4800-27-18, Revision 1, dated May 19, 2006, as an additional source of service information for accomplishing the modification required by paragraph (k) of this AD.

(l) Modifications done before the effective date of this AD in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-27-3136, dated January 12, 2006, are acceptable for compliance with the modification required by paragraph (k) of this AD.

(m) Concurrently with the modification required by paragraph (k) of this AD, modify the four elevator servo controls in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-27-3134, Revision 01, dated May 12, 2006 (for Model A330-200 and -300 series airplanes); or Airbus Service Bulletin A340-27-4132, dated October 13, 2005 (for Model A340-200 and -300 series airplanes); as applicable.

Note 2: Airbus Service Bulletins A330-27-3134 and A340-27-4132 refer to Goodrich Actuation Systems Service Bulletin SC4800-27-17, Revision 2, dated May 19, 2006, as an additional source of service information for accomplishing the modification required by paragraph (m) of this AD.

(n) Modifications done before the effective date of this AD in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-27-3134, dated October 13, 2005, are acceptable for compliance with the modification required by paragraph (m) of this AD.

(o) Accomplishment of the modifications required by paragraphs (k) and (m) of this AD constitutes terminating action for the requirements of paragraphs (f) through (i) of this AD.

Parts Installation

(p) As of the effective date of this AD, no person may install, on any airplane, an elevator servo control, unless it has been modified in accordance with paragraphs (k) and (m) of this AD.

Alternative Methods of Compliance (AMOCs)

(q)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(r) European Aviation Safety Agency airworthiness directive 2007-0008, dated January 9, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(s) You must use the applicable Airbus service information contained in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

Table 2 – All Material Incorporated by Reference

Service Information	Revision	Date
Airbus All Operators Telex A330-27A3138	01	October 3, 2005
Airbus All Operators Telex A340-27A4137	01	October 3, 2005
Airbus Service Bulletin A330-27-3134	01	May 12, 2006
Airbus Service Bulletin A330-27-3136	01	July 19, 2006
Airbus Service Bulletin A330-27-3138, excluding Appendix 01	02	May 30, 2006
Airbus Service Bulletin A340-27-4132	Original	October 13, 2005
Airbus Service Bulletin A340-27-4135	Original	January 12, 2006
Airbus Service Bulletin A340-27-4137, excluding Appendix 01	02	May 30, 2006

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 3 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

Table 3 – New Material Incorporated by Reference

Service Information	Revision	Date
Airbus Service Bulletin A330-27-3134	01	May 12, 2006
Airbus Service Bulletin A330-27-3136	01	July 19, 2006
Airbus Service Bulletin A330-27-3138, excluding Appendix 01	02	May 30, 2006
Airbus Service Bulletin A340-27-4132	Original	October 13, 2005
Airbus Service Bulletin A340-27-4135	Original	January 12, 2006
Airbus Service Bulletin A340-27-4137, excluding Appendix 01	02	May 30, 2006

(2) On November 29, 2005 (70 FR 69065, November 14, 2005), the Director of the Federal Register approved the incorporation by reference of Airbus All Operators Telex A330-27A3138, Revision 01, dated October 3, 2005; and Airbus All Operators Telex A340-27A4137, Revision 01, dated October 3, 2005.

(3) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 3, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-4671 Filed 3-11-08; 8:45 am]



2008-08-01 McCauley Propeller Systems: Amendment 39-15453. Docket No. FAA-2006-25173; Directorate Identifier 2006-NE-24-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 19, 2008.

Affected ADs

- (b) This AD supersedes AD 2003-15-01, Amendment 39-13243; AD 2003-17-10, Amendment 39-13285; and AD 2006-15-13, Amendment 39-14693.

Applicability

- (c) This AD applies to McCauley Propeller Systems propeller models B5JFR36C1101/114GCA-0, C5JFR36C1102/L114GCA-0, B5JFR36C1103/114HCA-0, and C5JFR36C1104/L114HCA-0. These propellers are installed on BAE Systems (Operations) Limited Jetstream Model 4100 and 4101 series airplanes (Jetstream 41).

Unsafe Condition

- (d) This AD results from our determination that we must require repetitive inspections for cracks, and from reports of blunt leading edges of the propeller blades due to erosion. We are issuing this AD to detect cracks in the propeller blade that could cause failure and separation of the propeller blade and loss of control of the airplane, and to detect blunt leading edges on the propeller blades, which could cause airplane single engine climb performance degradation and could result in an increased risk of collision with terrain.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Life Limit

- (f) Remove all 114GCA-0, L114GCA-0, 114HCA-0, and L114HCA-0 propeller blades upon reaching 10,000 operating hours time-since-new.

Initial Propeller Blade Inspection

- (g) Perform an initial fluorescent penetrant inspection and eddy current inspection of propeller blades. Use the Equipment Required and Accomplishment Instructions of McCauley Propellers Alert Service Bulletin ASB255, dated January 8, 2007, and the following compliance schedule:

Table 1. – Compliance Schedule

If the Propeller Blade:	Then Inspect the Propeller Blade:
(1) Has more than 2,400 operating hours time-since-new (TSN), time-since-last inspection (TSLI), or time-since-overhaul (TSO).	Within 100 operating hours time-in-service (TIS) after the effective date of this AD.
(2) Has 2,400 or fewer operating hours TSN, TSLI, or TSO.	Upon reaching 2,500 operating hours TSN, TSLI, or TSO.

Propeller Blades Found Cracked

(h) Remove from service propeller blades found with any crack indications. Blades found with crack indications are no longer eligible for installation in any configuration. Do not install them in any configuration on any airframe.

Repetitive Propeller Blade Inspection

(i) Thereafter, inspect the propeller blades within 2,500 operating hours TSLI or TSO. Use the Equipment Required and Accomplishment Instructions of McCauley Propellers Alert Service Bulletin ASB255, dated January 8, 2007.

Inspection for Blunt Erosion on the Leading Edge of the Propeller Blade

(j) Every time the propeller is removed for the inspection for cracks, inspect the blade for erosion and, if necessary, repair the erosion. The McCauley Propeller Systems Blade Overhaul Manual No., BOM 100, contains information on inspecting and repairing erosion on the propeller blade.

Reporting Requirements

(k) Within 10 calendar days of the inspection, use the Reporting Form for Service Bulletin 255 to report all inspection findings to McCauley Propeller Systems, P.O. Box 7704, Wichita, KS 67277-7704, telephone (800) 621-7767.

(l) The Office of Management and Budget (OMB) has approved the reporting requirements and assigned OMB control number 2120-0056.

Alternative Methods of Compliance

(m) The Manager, Wichita Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Special Flight Permits

(n) Under 39.23, we are limiting the availability of special flight permits for this AD. Special flight permits are available only if:

- (1) The operator has not seen signs of external oil leakage from the hub; and
 - (2) The operator has not observed abnormal propeller vibration or abnormal engine vibration;
- and
- (3) The operator has not observed any other abnormal operation from the propeller; and

(4) The operator has not made earlier reports of abnormal propeller vibration, abnormal engine vibration, or other abnormal propeller operations that have not been addressed.

Related Information

(o) Contact Jeff Janusz, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, Small Airplane Directorate, 1801 Airport Road, Room 100, Wichita, KS 67209; e-mail: jeff.janusz@faa.gov; telephone: (316) 946-4148; fax: (316) 946-4107, for more information about this AD.

Material Incorporated by Reference

(p) You must use the McCauley Propellers Alert Service Bulletin ASB255, dated January 8, 2007, to perform the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact McCauley Propeller Systems, P.O. Box 7704, Wichita, KS 67277-7704, telephone (800) 621-7767, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on March 31, 2008.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E8-7162 Filed 4-11-08; 8:45 am]



2008-08-02 Boeing: Amendment 39-15454. Docket No. FAA-2007-0227; Directorate Identifier 2007-NM-159-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Model 727, 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from reports of the threads cracking on the main landing gear (MLG) side strut lower segment. We are issuing this AD to prevent a fractured side strut, which could result in collapse of the MLG.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections and Corrective Actions

- (f) At the latest applicable time in paragraph (f)(1), (f)(2), or (f)(3) of this AD: Do detailed and magnetic particle inspections for cracking or corrosion of the threaded end of the lower segment of the MLG side strut and do all applicable corrective actions as specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 727-32-0338, Revision 4, dated April 7, 2007. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 120 months.

(1) Within 48 months after the last MLG overhaul.

(2) Within 6 months after the effective date of this AD.

(3) Within 120 months after the last MLG overhaul for airplanes on which the actions in Boeing Special Attention Service Bulletin 727-32-0338, Revision 4, dated April 7, 2007, have been accomplished before the effective date of this AD.

Prior/Concurrent Requirements

(g) Prior to or concurrently with the actions required by paragraph (f) of this AD: Do all applicable actions specified in the service bulletins listed in Table 1 of this AD. Where the lubrication and corrosion protection procedures in any service bulletin listed in Table 1 of this AD differ from those in Boeing Special Attention Service Bulletin 727-32-0338, Revision 4, dated April 7, 2007, use the procedures in Boeing Special Attention Service Bulletin 727-32-0338, Revision 4.

Table 1 – Prior/Concurrent Requirements

For –	Service Bulletin –	Describes procedures for these prior or concurrent actions –
(1) All airplanes	Boeing Special Attention 727-32-0411, Revision 1, dated February 19, 2007	Inspecting for corrosion or cracking of the threads and thread relief area of the swivel clevis, and improving the corrosion protection of the swivel clevis fitting threads in commonly affected airplanes
(2) Airplanes specified as Options III, IV and V configurations in Boeing Special Attention Service Bulletin 727-32-0338, Revision 4	Boeing 727 Service Bulletin 32-79, Revision 1, dated February 27, 1967	Modifying the MLG side strut universal joint
	Boeing 727 Service Bulletin 32-157, dated August 30, 1968	Replacing the MLG side strut swivel bushing, incorporating only parts kit 65-89855-1, and not installing the lube fitting in the lower segment
(3) Airplanes specified as Option V configuration in Boeing Special Attention Service Bulletin 727-32-0338, Revision 4	Boeing Service Bulletin 727-32-268, Revision 2, dated February 20, 1981	Inspecting and modifying the MLG side strut
	Boeing Service Bulletin 727-57-163, dated September 17, 1982	Resolving the interference between the MLG gear beam and the MLG side strut

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Material Incorporated by Reference

(i) You must use the applicable service information listed in Table 2 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Table 2 – Material Incorporated by Reference

Service Bulletin	Revision	Date
Boeing Special Attention Service Bulletin 727-32-0338	4	April 7, 2007
Boeing Special Attention Service Bulletin 727-32-0411	1	February 19, 2007
Boeing 727 Service Bulletin 32-157	Original	August 30, 1968
Boeing 727 Service Bulletin 32-79	1	February 27, 1967
Boeing Service Bulletin 727-32-268	2	February 20, 1981
Boeing Service Bulletin 727-57-163	Original	September 17, 1982

Issued in Renton, Washington, on March 28, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7176 Filed 4-11-08; 8:45 am]



2008-08-04 Airbus: Amendment 39-15456. Docket No. FAA-2008-0014; Directorate Identifier 2007-NM-249-AD.

Effective Date

- (a) This AD becomes effective May 19, 2008.

Affected ADs

- (b) This AD supersedes AD 2006-11-04.

Applicability

(c) This AD applies to Airbus Model A318, A319, A320, and A321 airplanes, certificated in any category, except airplanes on which Airbus Modification 32025 has been accomplished in production.

Unsafe Condition

(d) This AD results from cracks found in the forward lug of the main landing gear (MLG) support rib 5 fitting. We are issuing this AD to prevent cracking in the forward lug of the MLG, which could result in failure of the lug and consequent collapse of the MLG during takeoff or landing.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Certain Requirements of AD 2006-11-04

Repetitive Detailed Inspections

(f) Within 8 days after June 7, 2006 (the effective date of AD 2006-11-04), or before further flight after a hard landing, whichever is first: Perform a detailed inspection for cracking in the forward lug of the support rib 5 fitting of the left- and right-hand MLG, and, if any crack is found, replace the MLG fitting with a new fitting before further flight, in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent). Accomplishing the actions specified in the Airbus A318/A319/A320/A321 Nondestructive Testing Manual, Chapter 51-90-00, Revision dated February 1, 2003, is one approved method for performing the detailed inspection. Repeat the inspection thereafter at intervals not to exceed 8 days, or before further flight after a hard landing, whichever is first. As of the effective date of this AD, the repetitive inspections required by paragraph (i) of this AD must be accomplished in lieu of the repetitive inspections required by this paragraph.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Optional Inspection Method

(g) Performing an ultrasonic inspection for cracking in the forward lug of the support rib 5 fitting of the left- and right-hand MLG in accordance with a method approved by the Manager, International Branch, ANM-116; or the EASA (or its delegated agent); is an acceptable alternative method of compliance for the initial and repetitive inspections required by paragraph (f) of this AD. Doing the actions specified in the Airbus A318/A319/A320/A321 Nondestructive Testing Manual, Chapter 57-29-03, Revision dated February 1, 2005 (for Model A318, A319, and A320 airplanes), or Chapter 57-29-04, Revision dated May 1, 2005 (for Model A321 airplanes), as applicable, is one approved method for performing the ultrasonic inspection.

Optional Terminating Action

(h) For Model A319, A320, and A321 airplanes: Repair of the forward lugs of the support rib 5 fitting of the left- and right-hand MLG in accordance with a method approved by the Manager, International Branch, ANM-116; or the EASA (or its delegated agent); constitutes terminating action for the requirements of this AD. Doing the repair in accordance with Airbus A319 Structural Repair Manual (SRM), Chapter 5.C., 57-26-13, Revision dated November 1, 2004; Airbus A320 SRM, Chapter 5.D., 57-26-13, Revision dated November 1, 2004; or Airbus A321 SRM, Chapter 5.D., 57-26-13, Revision dated February 1, 2005; as applicable; is one approved method.

New Requirements of This AD

New Repetitive Inspections

(i) At the applicable time specified in Table 1 of this AD, or before further flight after a hard landing, whichever is first: Do a visual inspection or ultrasonic inspection for cracking in the forward lug of the support rib 5 fitting of the left and right MLG, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-57-1138, Revision 01, dated October 27, 2006. Repeat the inspection thereafter at the applicable interval specified in Table 1 of this AD or before further flight after a hard landing, whichever is first, until the modification required by paragraph (k) of this AD has been accomplished. Accomplishing the initial inspection terminates the requirements of paragraph (f) of this AD.

Table 1 – Compliance Times

Airplanes	Initial Inspection	Repetitive Interval
Model A318, A319, and A320 airplanes	If the most recent inspection is a detailed inspection done in accordance with paragraph (f) of this AD, inspect within 150 flight cycles after the most recent detailed inspection.	Within 150 flight cycles after a visual inspection
	If the most recent inspection is an ultrasonic inspection done in accordance with paragraph (g) of this AD, inspect within 940 flight cycles after the most recent ultrasonic inspection.	Within 940 flight cycles after an ultrasonic inspection
Model A321 airplanes	If the most recent inspection is a detailed inspection done in accordance with paragraph (f) of this AD, inspect within 100 flight cycles after the most recent detailed inspection.	Within 100 flight cycles after a visual inspection
	If the most recent inspection is an ultrasonic inspection done in accordance with paragraph (g) of this AD, inspect within 630 flight cycles after the most recent ultrasonic inspection.	Within 630 flight cycles after an ultrasonic inspection

Corrective Action

(j) If any cracking is found during any inspection required by paragraph (i) of this AD: Before further flight, repair or replace the cracked MLG fitting using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, or the EASA (or its delegated agent).

Terminating Action

(k) Within 60 months after the effective date of this AD, modify the rib bushings of the left and right MLG, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Airbus Service Bulletin A320-57-1118, Revision 03, dated April 23, 2007. Accomplishing the modification terminates the requirements of this AD.

Credit for Actions Done According to Previous Issue of Service Bulletin

(l) For Model A319, A320, and A321 airplanes, modifying the lugs of the support rib 5 fitting of the left and right MLG is acceptable for compliance with the requirements of paragraph (k) of this AD if done before the effective date of this AD in accordance with one of the following service bulletins: Airbus Service Bulletin A320-57-1118, dated September 5, 2002; Revision 01, dated August 28, 2003; or Revision 02, dated August 2, 2006.

Alternative Methods of Compliance (AMOCs)

(m)(1) The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006-11-04 are approved as AMOCs for the corresponding provisions of this AD.

Related Information

(n) EASA airworthiness directive 2007-0213, dated August 7, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(o) You must use Airbus Service Bulletin A320-57-1118, Revision 03, dated April 23, 2007; and Airbus Service Bulletin A320-57-1138, Revision 01, dated October 27, 2006; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 31, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7182 Filed 4-11-08; 8:45 am]



2008-08-05 Fokker Services B.V: Amendment 39-15457. Docket No. FAA-2007-0394; Directorate Identifier 2007-NM-252-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the Fokker airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Fokker Model F.27 Mark 050 airplanes, equipped with Honeywell International (Grimes Aerospace) Passenger Service Units (PSUs), part number 10-1178-XX series.

(2) Fokker Model F.28 Mark 0100 airplanes, equipped with Honeywell International (Grimes Aerospace) PSUs, part number 10-1178-XX series or 10-1571-XX series, unless modified in accordance with Fokker Service Bulletin SBF100-25-070.

Subject

- (d) Air Transport Association (ATA) of America Code 25: Equipment/Furnishings.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Recently, a Fokker 100 (F28 Mark 0100) operator noted that the electrical connectors of the PSUs (Passenger Service Units) did not lock properly during installation in the aircraft. The PSU panels installed in Fokker 50 (F27 Mark 050 and Mark 0502) aircraft are similar to those installed in the Fokker 100. Investigation revealed that the lack of locking is caused by the tolerance in thickness of the gaskets (seals) inside the PSU connectors. This condition, if not corrected, may cause the connector to overheat, leading to electrical arcing and subsequent failure of the PSU Panels. In such instances, smoke is likely to be emitted. To remedy and prevent these problems, the PSU manufacturer Honeywell International Aerospace Electronic Systems (formerly known as Grimes Aerospace Company), has narrowed the tolerances of these gaskets. Since an unsafe condition has been identified that is likely to exist or develop on aircraft of these type designs, this Airworthiness Directive requires inspection [to verify if the J1/P1 and J2/P2 interface connectors can be properly locked and gaskets are present] and, when necessary, replacement of the affected PSU Panel J1 and J2 Interface Connector gaskets.

Corrective actions include installing a gasket, verifying that the J1 and J2 receptacle locking tabs are not deformed, replacing the receptacle, and installing a new PSU panel.

Actions and Compliance

(f) Within 36 months after the effective date of this AD unless already done, do the following actions.

(1) Inspect the affected Honeywell International (Grimes Aerospace) PSU Panel Interface Connectors for proper locking of the connectors and to verify that gaskets are installed, in accordance with Part 3., "Accomplishment Instructions," of Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006, as applicable.

(2) When discrepancies are found, before next flight, do all applicable corrective actions as detailed in Part 3., "Accomplishment Instructions," of Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006, as applicable.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Dutch Airworthiness Directive NL-2006-008, dated July 14, 2006; and Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006; for related information.

Material Incorporated by Reference

(i) You must use Fokker Service Bulletin SBF50-25-061, dated March 31, 2006; or Fokker Service Bulletin SBF100-25-108, dated March 31, 2006; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 31, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7178 Filed 4-11-08; 8:45 am]



2008-08-06 Bombardier, Inc (Formerly Canadair): Docket No. FAA-2008-0408; Directorate Identifier 2008-NM-068-AD; Amendment 39-15458.

Effective Date

- (a) This AD becomes effective April 21, 2008.

Affected ADs

- (b) This AD supersedes AD 2005-04-07.

Applicability

(c) This AD applies to all Bombardier Model CL-600-1A11 (CL-600), CL-600-2A12 (CL-601), CL-600-2B16 (CL-601-3A, CL-601-3R, & CL-604) airplanes, and Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes, certificated in any category.

Note 1: Some Model CL-600-2B16 (CL-604) airplanes might be referred to by a marketing designation as CL-605.

Unsafe Condition

(d) This AD results from reports of uncommanded roll during take-off. We are issuing this AD to prevent possible loss of control on take-off resulting from even small amounts of frost, ice, snow, or slush on the wing leading edges or forward upper wing surfaces.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of AD 2005-04-07

Revision to Airplane Flight Manual (AFM)

(f) Within 5 days after February 22, 2005 (the effective date of AD 2005-04-07), revise the applicable Bombardier AFMs, Chapter 2 Limitations—Operating Limitations section, by inserting a copy of the new cold weather operations limitation specified in the Canadair (Bombardier) temporary revisions (TRs) listed in Table 1 of this AD. Thereafter, operate the airplanes per the limitation specified in the applicable TR, except as provided by paragraph (i) of this AD. Accomplishing the actions of paragraph (g) of this AD terminates the requirements of this paragraph.

Table 1.—TRs

Bombardier Model	TR	AFM
CL-600-1A11 (CL-600) series airplanes	600/21, February 4, 2005	PSP 600 (US).
CL-600-1A11 (CL-600) series airplanes	600-1/16, February 4, 2005	PSP 600-1 (US).
CL-600-2A12 (CL-601) series airplanes	601/13, February 4, 2005	PSP 601-1B-1.
CL-600-2A12 (CL-601) series airplanes	601/14, February 4, 2005	PSP 601-1A-1.
CL-600-2A12 (CL-601) series airplanes	601/18, February 4, 2005	PSP 601-1B.
CL-600-2A12 (CL-601) series airplanes	601/26, February 4, 2005	PSP 601-1A.
CL-600-2B16 (CL-601-3A and CL-601-3R) series airplanes	601/24, February 4, 2005	PSP 601A-1.
CL-600-2B16 (CL-601-3A and CL-601-3R) series airplanes	601/25, February 4, 2005	PSP 601A-1-1.
CL-600-2B16 (CL-604) series airplanes	604/17, February 4, 2005	PSP 604-1.
CL-600-2B19 (Regional Jet Series 100 & 440)	RJ/149-1, February 1, 2005	CSP A-012.

Note 2: When information identical to that in a TR specified in paragraph (f) of this AD has been included in the general revisions of the applicable AFM, the general revisions may be inserted into the AFM, and the TR may be removed from that AFM.

New Requirements of This AD

(g) Within 7 days after the effective date of this AD, revise the applicable sections of the applicable AFM by inserting a copy of the applicable TR listed in Table 2 of this AD. Thereafter, operate the airplanes per the limitation specified in the applicable TR, except as provided by paragraph (i) of this AD. Once the applicable temporary revision required by this paragraph is inserted in the AFM, the applicable revision required by paragraph (f) of this AD must be removed from the AFM.

(h) When information identical to that in a TR specified in paragraph (g) of this AD has been included in the general revisions of the applicable AFM, the general revisions may be inserted into the AFM, and the TR may be removed from that AFM.

Table 2.—Temporary Revisions

For Bombardier Model—	Use—	Dated—	To the—
CL-600-1A11 (CL-600) airplanes	Canadair Temporary Revision 600/25-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-1A11 AFM.
CL-600-1A11 (CL-600) airplanes	Canadair Temporary Revision 600-1/20-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-1A11 AFM (Winglets).

CL-600-2A12 (CL-601) airplanes	Canadair Temporary Revision 601/17-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2A12 AFM, PSP 601-1B-1.
CL-600-2A12 (CL-601) airplanes	Canadair Temporary Revision 601/18-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2A12 AFM, PSP 601-1A-1.
CL-600-2A12 (CL-601) airplanes	Canadair Temporary Revision 601/22-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2A12 AFM, PSP 601-1B.
CL-600-2A12 (CL-601) airplanes	Canadair Temporary Revision 601/30-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2A12 AFM.
CL-600-2B16 (CL-601-3A, and CL-601-3R) airplanes.	Canadair Temporary Revision 601/29-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2B16 AFM, PSP 601A-1.
CL-600-2B16 (CL-601-3A, and CL-601-3R) airplanes.	Canadair Temporary Revision 601/30-1.	March 20, 2008	Limitations and Normal Procedures sections of Canadair Challenger CL-600-2B16 AFM, PSP 601A-1-1.
CL-600-2B16 (CL-604) airplanes, serial numbers 5301 through 5699.	Bombardier Temporary Revision 604/24-1.	March 20, 2008	Limitations and Normal Procedures sections of Bombardier Challenger CL-604 AFM, PSP 604-1.
CL-600-2B16 (CL-604) airplanes, serial numbers 5701 and subsequent.	Bombardier Temporary Revision 605/1-1.	March 20, 2008	Limitations and Normal Procedures sections of Bombardier Challenger CL-605 AFM, PSP 605-1.
CL-600-2B19 (Regional Jet Series 100 & 440) airplane.	Canadair Temporary Revision RJ/155-3.	March 25, 2008	Limitations and Abnormal Procedures sections and Supplement 15 of Canadair Regional Jet AFM, CSP A-012.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, New York Aircraft Certification Office (ACO) FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19. Send information to ATTN: Bruce Valentine, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7328; fax (516) 794-5531.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(j) Canadian emergency airworthiness directives CF-2008-15, dated March 7, 2008, and CF-2008-16, dated March 10, 2008, also address the subject of this AD.

Material Incorporated by Reference

(k) You must use the applicable temporary revision to the applicable airplane flight manual specified in Tables 3 and 4 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 3 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On February 22, 2005 (70 FR 8025, February 17, 2005), the Director of the Federal Register approved the incorporation by reference of the documents listed in Table 4 of this AD.

(3) Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Table 3.—New Material Incorporated by Reference

Temporary revisions	Date	Airplane flight manual
Canadair Temporary Revision 600/25–1	March 20, 2008	Canadair Challenger CL–600–1A11 Airplane Flight Manual.
Canadair Temporary Revision 600–1/20–1.	March 20, 2008	Canadair Challenger CL–600–1A11 Airplane Flight Manual (Winglets).
Canadair Temporary Revision 601/17–1	March 20, 2008	Canadair Challenger CL–600–2A12 Airplane Flight Manual, PSP 601–1B–1.
Canadair Temporary Revision 601/18–1	March 20, 2008	Canadair Challenger CL–600–2A12 Airplane Flight Manual, PSP 601–1A–1.
Canadair Temporary Revision 601/22–1	March 20, 2008	Canadair Challenger CL–600–2A12 Airplane Flight Manual, PSP 601–1B
Canadair Temporary Revision 601/30–1	March 20, 2008	Canadair Challenger CL–600–2A12 Airplane Flight Manual.
Canadair Temporary Revision 601/29–1	March 20, 2008	Canadair Challenger CL–600–2B16 Airplane Flight Manual, PSP 601A–1.
Canadair Temporary Revision 601/30–1	March 20, 2008	Canadair Challenger CL–600–2B16 Airplane Flight Manual, PSP 601A–1–1.

Bombardier Temporary Revision 604/24-1.	March 20, 2008	Bombardier Challenger CL-604 Airplane Flight Manual, PSP 604-1.
Bombardier Temporary Revision 605/1-1.	March 20, 2008	Bombardier Challenger CL-605 Airplane Flight Manual, PSP 605-1
Canadair Temporary Revision RJ/155-3	March 25, 2008	Canadair Regional Jet Airplane Flight Manual, CSP A-012.

Table 4.—Previous Material Incorporated by Reference

Canadair (Bombardier) temporary revision	Bombardier airplane flight manual
RJ/149-1, February 1, 2005	CL-600-2B19 (Regional Jet Series 100 & 440), CSP A-012.
600/21, February 4, 2005	CL-600-1A11 (CL-600), PSP 600 (US).
600-1/16, February 4, 2005	CL-600-1A11 (CL-600), PSP 600-1 (US).
601/13, February 4, 2005	CL-600-2A12 (CL-601), PSP 601-1B-1.
601/14, February 4, 2005	CL-600-2A12 (CL-601), PSP 601-1A-1.
601/18, February 4, 2005	CL-600-2A12 (CL-601), PSP 601-1B
601/24, February 4, 2005	CL-600-2B16 (CL-601-3A and CL-601-3R), PSP 601A-1.
601/25, February 4, 2005	CL-600-2B16 (CL-601-3A and CL-601-3R), PSP 601A-1-1.
601/26, February 4, 2005	CL-600-2A12 (CL-601), PSP 601-1A.
604/17, February 4, 2005	CL-600-2B16 (CL-604), PSP 604-1.

Issued in Renton, Washington, on April 2, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7592 Filed 4-11-08; 8:45 am]



2008-08-07 Saab Aircraft AB: Amendment 39-15459. Docket No. FAA-2007-29331; Directorate Identifier 2007-NM-136-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to the airplanes listed in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, unless equipped with main landing gear (MLG) shock struts modified in accordance with APPH Service Bulletin AIR83064-32-12 or AIR83022-32-32.

(1) Saab Model SAAB-Fairchild SF340A (SAAB/SF340A) airplanes, serial numbers (S/Ns) SF340A-004 through -159.

(2) Saab Model SAAB 340B airplanes, S/Ns 340B-160 through -459.

Subject

- (d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

A crack has been found in an axle adaptor during fatigue testing. It was found that the internal edges of the dowel holes did not have the correct radius and the crack had developed from the edge of one of the dowel holes.

A crack in the axle adaptor can cause the axle adaptor to fail and ultimately lead to loss of [the] wheels and total loss of brake capability.

The corrective action includes doing repetitive ultrasonic inspections to detect cracking in the axle adaptor; replacing the axle adaptor if necessary; and ultimately doing the terminating action of inspecting and modifying the main landing gear (MLG) shock strut and axle adaptors. The inspection is a crack test. The modification includes measuring the dowel hole and corrective actions if necessary (replacing the axle adaptor, repairing the dowel hole), and, when accomplished, terminates the repetitive inspection requirements.

Actions and Compliance

- (f) Unless already done, do the following actions.

(1) Within 8,000 flight cycles since the last MLG overhaul, or within 1,500 flight cycles, or 6 months after the effective date of this AD, whichever occurs latest: Inspect the MLG in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-32-133, Revision 01, dated May 3, 2006. If any crack is found, before further flight: Replace the axle adaptor in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-32-133, Revision 01, dated May 3, 2006.

(2) Repeat the inspection required by paragraph (f)(1) of this AD thereafter at intervals not to exceed 2,000 flight cycles until the terminating action required by paragraph (f)(3) of this AD is accomplished.

(3) Within 12,000 flight cycles after the effective date of this AD, or at the next MLG overhaul, whichever occurs earlier: Inspect and modify the MLG shock strut and axle adaptors in accordance with the Accomplishment Instructions of APPH Service Bulletin AIR83064-32-12, Revision 3, dated April 26, 2006; or AIR83022-32-32, Revision 3, dated April 26, 2006; as applicable.

(4) Actions done before the effective date of this AD in accordance with the service bulletins listed in paragraphs (f)(4)(i), (f)(4)(ii), and (f)(4)(iii) of this AD, as applicable, are acceptable for compliance with the corresponding actions in this AD.

(i) Saab Service Bulletin 340-32-133, dated April 19, 2006.

(ii) APPH Service Bulletin AIR83064-32-12, dated January 2006; Revision 1, dated January 23, 2006; and Revision 2, dated March 30, 2006.

(iii) APPH Service Bulletin AIR83022-32-32, dated January 2006; Revision 1, dated January 23, 2006; and Revision 2, dated March 30, 2006.

(5) As of the effective date of this AD, no person may install an MLG shock strut having part number (P/N) AIR83022 or AIR83064, or axle adaptor having P/N AIR127308, AIR390226, or AIR130238, unless it has been inspected and modified in accordance with APPH Service Bulletin AIR83022-32-32 or AIR83064-32-12, as specified in paragraph (f)(3), (f)(4)(ii), or (f)(4)(iii) of this AD, as applicable.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Borfitz, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2677; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2006-0263, dated August 29, 2006; Saab Service Bulletin 340-32-133, Revision 01, dated May 3, 2006; APPH Service Bulletin AIR83064-32-12, Revision 3, dated April 26, 2006; and APPH Service Bulletin AIR83022-32-32, Revision 3, dated April 26, 2006; for related information.

Material Incorporated by Reference

(i) You must use the service information specified in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Table 1 – Material Incorporated by Reference

Service Bulletin	Revision	Date
APPH Service Bulletin AIR83022-32-32	3	April 26, 2006
APPH Service Bulletin AIR83064-32-12	3	April 26, 2006
Saab Service Bulletin 340-32-133	01	May 3, 2006

Issued in Renton, Washington, on March 31, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7299 Filed 4-11-08; 8:45 am]



FAA
Aircraft Certification Service

AIRWORTHINESS DIRECTIVE

www.faa.gov/aircraft/safety/alerts/
www.gpoaccess.gov/fr/advanced.html

2008-08-08 Boeing: Amendment 39-15460. Docket No. FAA-2008-0011; Directorate Identifier 2007-NM-203-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Boeing Model 757-200, -200CB, -200PF, and -300 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 757-35-0028, dated April 9, 2007.

Unsafe Condition

- (d) This AD results from a report that several passenger masks with broken in-line flow indicators were found following a mask deployment. We are issuing this AD to prevent the in-line flow indicators of the passenger oxygen masks from fracturing and separating, which could inhibit oxygen flow to the masks and consequently result in exposure of the passengers and cabin attendants to hypoxia following a depressurization event.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective/Other Specified Actions if Necessary

- (f) Within 60 months after the effective date of this AD, do a general visual inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service units and the lavatory and attendant box assemblies, and do the applicable corrective action, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 757-35-0028, dated April 9, 2007; except where the service bulletin specifies repairing the oxygen mask assembly, replace it with a new or modified oxygen mask assembly having an improved flow indicator. The corrective action and other specified action must be done before further flight.

Note 1: The service bulletin refers to B/E Aerospace Service Bulletin 174080-35-01, dated February 6, 2006; and Revision 1, dated May 1, 2006; as additional sources of service information for modifying the oxygen mask assembly by replacing the flow indicator with an improved flow indicator.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Boeing Special Attention Service Bulletin 757-35-0028, dated April 9, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 31, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7297 Filed 4-11-08; 8:45 am]



2008-08-09 Bombardier, Inc. (Formerly Canadair): Amendment 39-15461. Docket No. FAA-2008-0047; Directorate Identifier 2007-NM-295-AD.

Effective Date

- (a) This AD becomes effective May 19, 2008.

Affected ADs

- (b) This AD supersedes AD 2006-05-11 R1.

Applicability

(c) This AD applies to Bombardier Model CL-600-2B19 (Regional Jet Series 100 & 400) airplanes, certificated in any category, serial numbers 7003 through 7990 inclusive, and 8000 and subsequent.

Unsafe Condition

(d) This AD results from a report that the shear pin located in the input lever of two pitch feel simulator (PFS) units failed due to fatigue. We are issuing this AD to prevent undetected failure of the shear pins of both PFS units simultaneously, which could result in loss of pitch feel forces and consequent reduced control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2006-05-11 R1

Revise Airworthiness Limitations (AWL) Section of Maintenance Requirements Manual

(f) For airplanes having serial numbers 7003 through 7990 inclusive: Within 14 days after February 13, 2004 (the effective date of AD 2004-02-07, which was superseded by AD 2006-05-11 R1), revise the AWL section of the Instructions for Continued Airworthiness of the maintenance requirements manual by incorporating the functional check of the PFS pilot input lever, Task R27-31-A024-01, as specified in Bombardier Temporary Revision (TR) 2B-1784, dated October 24, 2003, to the CL-600-2B19 Canadair Regional Jet Maintenance Requirements Manual, Part 2, Appendix B, "Airworthiness Limitations," into the AWL section.

New Repetitive Functional Tests and Corrective Actions

(g) Before the accumulation of 4,000 total flight hours, or within 100 flight hours after March 27, 2006 (the effective date of AD 2006-05-11 R1), whichever occurs later: Do a functional test of the pilot input lever of the PFS units to determine if the lever is disconnected, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-27-144, Revision A, dated February 14, 2006, including Appendix A, dated September 15, 2005, except as required by paragraph (j) of this AD. Repeat the test at intervals not to exceed 100 flight hours. Accomplishing the initial functional test terminates the requirements of paragraph (f) of this AD and the repetitive functional checks of the PFS pilot input lever, Task R27-31-A024-01, as specified in the AWL section of the Instructions for Continued Airworthiness of CL-600-2B19 Canadair Regional Jet Maintenance Requirements Manual.

(h) If any lever is found to be disconnected during any functional test required by paragraph (g) of this AD, do the actions specified in paragraphs (h)(1) and (h)(2) of this AD in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R-27-144, Revision A, dated February 14, 2006, including Appendix A, dated September 15, 2005, except as required by paragraph (j) of this AD.

(1) Before further flight, replace the defective PFS with a serviceable PFS in accordance with the Accomplishment Instructions of the alert service bulletin; and

(2) Within 30 days after removing the defective PFS, submit a test report to the manufacturer in accordance with the Accomplishment Instructions of the alert service bulletin. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

Previously Accomplished Actions

(i) Actions done before March 27, 2006, in accordance with Bombardier Alert Service Bulletin A601R-27-144, including Appendix A, dated September 15, 2005, are acceptable for compliance with the requirements of paragraph (g) of this AD.

New Requirements of This AD

New Service Bulletin for Functional Tests

(j) As of the effective date of this AD, Bombardier Alert Service Bulletin A601R-27-144, Revision B, dated December 20, 2006, including Appendix A, Revision A, dated December 20, 2006, must be used for the actions required by paragraphs (g) and (h) of this AD.

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(l) Canadian airworthiness directive CF-2005-41, dated December 22, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(m) You must use the applicable service information listed in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise.

Table 1 – Material Incorporated by Reference

Bombardier Service Information	Revision Level	Date
Alert Service Bulletin A601R-27-144, including Appendix A, dated September 15, 2005	A	February 14, 2006
Alert Service Bulletin A601R-27-144, including Appendix A, Revision A, dated December 20, 2006	B	December 20, 2006
Temporary Revision 2B-1784 to the CL-600-2B19 Canadair Regional Jet Maintenance Requirements Manual, Part 2, Appendix B, "Airworthiness Limitations"	Original	October 24, 2003

(1) The Director of the Federal Register approved the incorporation by reference of Bombardier Alert Service Bulletin A601R-27-144, Revision B, dated December 20, 2006, including Appendix A, Revision A, dated December 20, 2006, in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On March 27, 2006 (71 FR 12277, March 10, 2006), the Director of the Federal Register approved the incorporation by reference of Bombardier Alert Service Bulletin A601R-27-144, Revision A, dated February 14, 2006, including Appendix A, dated September 15, 2005.

(3) On February 13, 2004 (69 FR 4234, January 29, 2004), the Director of the Federal Register approved the incorporation by reference of Bombardier Temporary Revision 2B-1784, dated October 24, 2003, to the CL-600-2B19 Canadair Regional Jet Maintenance Requirements Manual, Part 2, Appendix B, "Airworthiness Limitations."

(4) Contact Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 31, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7294 Filed 4-11-08; 8:45 am]



2008-08-10 Boeing: Amendment 39-15462. Docket No. FAA-2007-29062; Directorate Identifier 2007-NM-020-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from reports of findings of fatigue cracking of the outboard stabilizing fitting and stress corrosion cracking of the bolts attaching the fitting to the wing rear spar. We are issuing this AD to detect and correct that cracking, which could result in disconnection of the MLG actuator from the rear spar and support beam, consequent damage to the hydraulic system, and possible loss of the "A" and "B" hydraulic systems and damage or jamming of the flight control cables. Damage or jamming of the flight control cables could result in loss of control of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Bulletin Reference

- (f) The term "alert service bulletin" as used in this AD, means the Accomplishment Instructions of Boeing Alert Service Bulletin 737-57A1266, Revision 1, dated January 3, 2007.

Replacement/Repetitive Inspections

- (g) For airplanes identified as Groups 1 through 8, as specified in the alert service bulletin, except as provided by paragraphs (h) and (k) of this AD: Within 36 months after the effective date of this AD, replace the outboard stabilizing fitting, H-11 bolts, forward pin, and aft pin, as applicable, with new components by doing all the applicable actions in accordance with Part II of the alert service bulletin, except as provided by paragraph (j) of this AD. Within 120 months after accomplishing the replacement, do a general visual inspection for discrepancies of the outboard stabilizing fitting, walking beam hanger, and rear spar attachment fitting, and do all applicable corrective actions, by doing all the actions, except as provided by paragraph (j) of this AD, in

accordance with Part V of the alert service bulletin. Do all corrective actions before further flight. Repeat the inspection at intervals not to exceed 120 months.

Alternative Inspection

(h) For airplanes identified as Groups 1 through 8, as specified in the alert service bulletin, on which the existing H-11 bolts were replaced before the effective date of this AD with Inconel 718 bolts, in lieu of doing the actions required by paragraph (g) of this AD: Within 4,500 flight cycles or 36 months after the effective date of this AD, whichever is later, do a magnetic test of the attach bolts in accordance with the alert service bulletin. If any bolt is magnetic, discontinue the alternative inspection specified in the alert service bulletin and accomplish the actions required by paragraph (g) before further flight. If none of the bolts are magnetic, do all the applicable actions in accordance with Part I of the alert service bulletin before further flight.

(1) If any crack is found: Stop the inspection and before further flight do the actions required by paragraph (g) of this AD. Repetitive inspections must be done after replacing the fitting at the interval specified in paragraph (g) of this AD.

(2) If no crack is found: Before further flight, replace the forward pin and aft pin, as applicable, in accordance with the alert service bulletin, and within 60 months after the effective date of this AD, do the remaining replacement required by paragraph (g) of this AD. Repetitive inspections must be done after replacing the fitting at the interval specified in paragraph (g) of this AD.

(3) If damage other than cracking is found, or if the fitting lug hole is beyond hole size limits, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

General Visual Inspection

(i) For airplanes identified as Group 9, as specified in the alert service bulletin: Within 36 months or 4,500 flight cycles after the effective date of this AD, whichever occurs later, do a general visual inspection of the outboard stabilizing fitting and fasteners for discrepancies, and do all applicable corrective actions in accordance with Part IV of the alert service bulletin, except as provided by paragraphs (j) and (k) of this AD. Within 120 months after the inspection specified in Part IV has been done, do a general visual inspection for discrepancies of the outboard stabilizing fitting, walking beam hanger and rear spar attachment fitting in accordance with Part V of the alert service bulletin, and do all applicable corrective actions in accordance with Part V of the alert service bulletin, except as provided by paragraphs (j) and (k). Do all applicable corrective actions before further flight. Repeat the Part V inspection at intervals not to exceed 120 months.

Exceptions To Alert Service Bulletin Specifications

(j) During any inspection required by this AD, if any corrosion damage is found that cannot be removed, or if any damage is found that is outside the limits specified in the alert service bulletin, or if any discrepancy is found and the alert service bulletin specifies contacting the manufacturer for disposition of certain repair conditions: Before further flight, repair using a method approved in accordance with the procedures specified in paragraph (p) of this AD.

(k) Certain sections in Parts I, II, and V of the alert service bulletin specify "For 737-100 and -200 airplanes" and "For 737-300 and -500 airplanes." However, those sections are applicable to Model 737-100, -200, and -200C airplanes, and Model 737-300, -400, and -500 airplanes, respectively.

Torque Check

(l) For airplanes identified as Groups 1 through 5, as specified in the alert service bulletin, on which the aft pin of the aft outboard stabilizing fitting was replaced before the effective date of this AD, in accordance with Boeing Alert Service Bulletin 737-57A1266, dated May 8, 2003: Within 36 months after the effective date of this AD, do a torque check to determine whether the aft pin is correctly installed. Do all applicable corrective actions before further flight. Do the actions in accordance with Part III of the alert service bulletin.

Concurrent Requirements

(m) For airplanes identified as Groups 1 and 3, as specified in the alert service bulletin: Prior to or concurrently with accomplishment of paragraph (g) of this AD, do the replacement of the existing tube assembly of the outboard stabilizing fitting as specified in Part IV of Boeing Service Bulletin 737-57-1052, Revision 4, dated October 24, 1980.

Credit for Previously Accomplished Actions

(n) Replacement of the tube assembly before the effective date of this AD in accordance with Boeing Service Bulletin 737-57-1073, Revision 4, dated April 12, 1985, is acceptable for compliance with the replacement specified in paragraph (m) of this AD.

(o) For Groups 1 through 4, as specified in the alert service bulletin: Replacement of the H-11 bolts for the inboard stabilizing fitting before the effective date of this AD, in accordance with Boeing Service Bulletin 737-57-1231, dated December 1, 1994, is acceptable for compliance with the replacement of the H-11 bolts specified in paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(p)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

Material Incorporated by Reference

(q) You must use Boeing Alert Service Bulletin 737-57A1266, Revision 1, dated January 3, 2007; and Boeing Service Bulletin 737-57-1052, Revision 4, dated October 24, 1980; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on March 24, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7561 Filed 4-11-08; 8:45 am]



2008-08-12 Boeing: Amendment 39-15464. Docket No. FAA-2007-0339; Directorate Identifier 2007-NM-182-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Boeing Model 757-200, -200PF, -200CB, and -300 series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD results from reports of cracks found at the anchor tab of the bulkhead seal assemblies of the wing thermal anti-ice (TAI) system. In one incident, the anchor tab and bulkhead seal assembly had separated because of the cracks. We are issuing this AD to prevent failure of the anchor tab of the bulkhead seal assembly, which in icing conditions could result in insufficient airflow to the wing TAI system, subsequent ice on the wings, and consequent reduced controllability of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Repetitive Inspections/Corrective Action

- (f) At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 757-30-0021 or 757-30-0022, both Revision 1, both dated June 13, 2007, as applicable; except where the service bulletins specify starting the compliance time " * * * from the date on this service bulletin," this AD requires starting the compliance time from the effective date of this AD: Perform detailed inspections for cracks of the anchor tab of the bulkhead seal assemblies of the wing TAI system at certain outboard stations of the left and right wings by doing all the actions, including all applicable corrective actions, in accordance with the Accomplishment Instructions of the applicable service bulletin. Do all applicable corrective actions before further flight.

Optional Terminating Action

- (g) Installing a new duct anchor support bracket adjacent to the bulkhead seal assemblies in accordance with Part 2 of the Accomplishment Instructions of Boeing Special Attention Service

Bulletin 757-30-0021 or 757-30-0022, both Revision 1, both dated June 13, 2007, as applicable, ends the repetitive inspections required by paragraph (f) of this AD.

Credit for Actions Done According to Previous Issue of Service Information

(h) Actions accomplished before the effective date of this AD in accordance with Boeing Special Attention Service Bulletins 757-30-0021 and 757-30-0022, both dated August 15, 2006, are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(j) You must use Boeing Special Attention Service Bulletin 757-30-0021, Revision 1, dated June 13, 2007; or Boeing Special Attention Service Bulletin 757-30-0022, Revision 1, dated June 13, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 3, 2008.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-7662 Filed 4-11-08; 8:45 am]



2008-08-13 Airbus: Amendment 39-15465. Docket No. FAA-2007-0345; Directorate Identifier 2007-NM-194-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 19, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Airbus Model A310-304, -322, -324, and -325 airplanes, certificated in any category, all serial numbers, except those which have received in service application of Airbus Service Bulletin A310-53-2126 (Airbus modification No. 13011). This AD also applies to Airbus A300 Model B4-601, B4-603, B4-605R, B4-620, B4-622, B4-622R, F4-605R, F4-622R, and C4-605R Variant F airplanes (commonly called Model A300-600 series airplanes), certificated in any category, all serial numbers, except those which have received application of Airbus modification No. 13273 in production or application of Airbus Service Bulletin A300-53-6156 in service.

Subject

- (d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Due to the recalculation of loads for the Multi Role Transporter and Tanker (MRTT) aircraft, it has been found that a structural reinforcement at the aft section of the fuselage (FR (frame) 87-FR91) is required for A300-600 aircraft and A310 aircraft with a Trim Tank installed.

* * * * *

The unsafe condition is the potential loss of structural integrity in the aft section of the fuselage between FR87 through FR91, inclusive, during extreme rolling and vertical maneuver combinations. The corrective action is reinforcing the structure at FR91. Related investigative and corrective actions (reinforcement) include:

- Doing a rotating probe inspection for cracking of the fastener holes;
- reaming the fastener holes; and
- contacting Airbus for repair instructions and repairing any crack found in any reamed fastener hole.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 2,500 flight cycles after the effective date of this AD, reinforce the aft section of the fuselage, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-53-2126, Revision 01, dated May 31, 2007; and Airbus Service Bulletin A300-53-6156, Revision 01, dated July 4, 2007; as applicable. Do all related and investigative corrective actions, as applicable, before further flight. Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A310-53-2126 or Airbus Service Bulletin A300-53-6156, both dated November 28, 2006, are considered acceptable for compliance with the corresponding action specified in this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No difference.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2007-0173, dated June 18, 2007; Airbus Service Bulletin A310-53-2126, Revision 01, dated May 31, 2007; and Airbus Service Bulletin A300-53-6156, Revision 01, dated July 4, 2007; for related information.

Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A310-53-2126, Revision 01, dated May 31, 2007; or Airbus Service Bulletin A300-53-6156, Revision 01, dated July 4, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For

information on the availability of this material at NARA, call (202) 741-6030, or go to:
<http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 3, 2008.
Dionne Palermo,
Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. E8-7665 Filed 4-11-08; 8:45 am]



2008-08-14 Precision Airmotive LLC: Amendment 39-15466. Docket No. FAA-2008-0420; Directorate Identifier 2008-NE-10-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective April 29, 2008, to all persons except those persons to whom it was made immediately effective by emergency AD 2008-06-51, issued March 12, 2008, which contained the requirements of this amendment.

Affected ADs

(b) This AD supersedes AD 2008-06-51.

Applicability

(c) This AD applies to the following reciprocating engines with an installed Precision Airmotive LLC, RSA-5 or RSA-10 series fuel injection servo, having a servo plug gasket, part number (P/N) 365533, installed under the fuel injection servo plug, P/N 383493:

(1) Lycoming Engines IO, (L)IO, TIO, (L)TIO, AEIO, AIO, IGO, IVO, and HIO series reciprocating engines, regardless of displacement, either new, rebuilt, overhauled, or repaired since August 22, 2006, and/or with an affected fuel injection servo installed either new, rebuilt, overhauled, or repaired since August 22, 2006.

(2) Teledyne Continental Motors TSIO-360-RB reciprocating engines, either new, rebuilt, overhauled, or repaired since August 22, 2006, and/or with an affected fuel injection servo installed either new, rebuilt, overhauled, or repaired since August 22, 2006.

(3) Superior Air Parts, Inc. IO-360 series reciprocating engines, either new, rebuilt, overhauled, or repaired since August 22, 2006, and/or with an affected fuel injection servo installed either new, rebuilt, overhauled, or repaired since August 22, 2006.

(4) This AD also applies to any other Precision Airmotive LLC fuel injection servos received since August 22, 2006, or any fuel injection servos that have had the fuel injection servo plug, P/N 383493, removed during maintenance since August 22, 2006.

Unsafe Condition

(d) This AD results from eighteen reports of fuel injection servo plugs, P/N 383493, that had loosened or completely backed out of the threaded plug hole on the regulator cover of the fuel injection servo. We are issuing this AD to prevent a lean running engine, which could result in a substantial loss of engine power and subsequent loss of control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed before further flight, unless the actions have already been done. The actions required by this AD must be done by an FAA-licensed mechanic.

Initial Inspection

(f) Inspect the fuel injection servo plug, P/N 383493, for looseness, by attempting to turn it by hand, while being careful not to damage the safety wire or seal. If the plug moves, it is loose.

(g) If the plug is not loose, go to paragraph (i) of this AD.

(h) If the plug is loose, do the following:

(1) Carefully cut and remove the safety wire that spans between the servo plug and regulator cover only.

(2) Remove the servo plug while ensuring that the gasket, P/N 365533, that is behind the plug, is not lost. The gasket may be slightly stuck to the regulator cover.

(3) Examine the threads on the servo plug and regulator cover for damage. Threads should be smooth and consistent, with no burrs or chips. The servo plug outer diameter threads should also measure within 0.7419-0.7500-inch.

(4) If the threads on either the servo plug or the regulator cover are damaged, or do not measure within the limits in paragraph (h)(3) of this AD, the servo is not eligible for any installation and must be replaced before further flight.

(5) Inspect the gasket, P/N 365533, for tears and other damage. We are allowing the re-use of undamaged gaskets. Replace damaged gaskets with a new gasket, P/N 365533.

(6) When reassembling, do not install any servo plug or regulator cover that is not eligible for installation. Install the gasket onto the servo plug and reassemble the servo plug to the regulator cover.

(7) Torque the servo plug to a new, higher torque of 90-100 in-lbs, to help maintain the proper clamp-up force against the plug and cover.

(8) Safety wire the servo plug with 0.025-inch diameter wire to the regulator cover. Information on properly safety wiring the plug can be found in Precision Airmotive LLC Mandatory Service Bulletin No. PRS-107, Revision 1, dated March 6, 2008.

(9) Inspect all other safety wire on the servo. Replace any that are damaged.

Repetitive Inspections

(i) At every engine oil change or within every 50 hours of engine run time, whichever occurs first, repeat the inspection and remedial steps specified in paragraphs (f) through (h)(9) of this AD.

Special Flight Permits Prohibited

(j) Under 14 CFR part 39.23, we are prohibiting special flight permits.

Alternative Methods of Compliance

(k) The Manager, Seattle Aircraft Certification Office, may approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(l) Precision Airmotive LLC Mandatory Service Bulletin No. PRS-107, Revision 1, dated March 6, 2008, pertains to the subject of this AD. You can get the service information identified in this AD from <http://www.precisionairmotive.com>.

(m) For Precision Airmotive LLC, Richard Simonson, Aerospace Engineer, Propulsion Branch, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055; e-mail: Richard.simonson@faa.gov; telephone: (425) 917-6507; fax: (425) 917-6590.

(n) For Lycoming Engines, Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; e-mail: Norman.perenson@faa.gov; telephone: (516) 228-7337; fax: (516) 794-5531.

(o) For Teledyne Continental Motors, Kevin Brane, Aerospace Engineer, Atlanta Aircraft Certification Office, FAA, Small Airplane Directorate, One Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta, GA 30349; e-mail: kevin.brane@faa.gov; telephone: (770) 703-6063; fax: (770) 703-6097.

(p) For Superior Air Parts, Inc., Tausif Butt, Aerospace Engineer, Special Certification Office, FAA, Rotorcraft Directorate, Southwest Regional Headquarters, 2601 Meacham Blvd., Fort Worth, Texas 76137; e-mail: Tausif.butt@faa.gov; telephone: (817) 222-5195; fax: (817) 222-5785.

Issued in Burlington, Massachusetts, on April 4, 2008.
Francis A. Favara,
Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. E8-7574 Filed 4-11-08; 8:45 am]



2008-08-18 Fokker Services B.V.: Amendment 39-15472. Docket No. FAA-2008-0117; Directorate Identifier 2007-NM-273-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Fokker Model F.28 Mark 0070 and Mark 0100 airplanes, certificated in any category, all serial numbers, except those previously modified in accordance with Fokker Service Bulletin SBF100-30-022.

Subject

- (d) Air Transport Association (ATA) of America Code 30: Ice and Rain Protection.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

In 1997, Fokker introduced a new type of Peri-seal (SBF100-30-022). The old type was known to be subject to deterioration, which, in combination with improper installation, can cause leakage of hot wing anti-icing air from the Peri-seal housing. This results in an uncontrolled flow of high-pressure hot air to enter the forward (anti-icing) plenum chamber of the wing leading edge, potentially damaging the anti-icing barrier webs. Subsequently, the wing auxiliary spar can also be damaged by high-pressure hot air. Analysis at the time showed that any resulting damage (known to occur at inboard positions only) would not affect the wing load capability. For this reason, the modification was not classified as MANDATORY and no AD action was warranted. However, through a recent occurrence, it was discovered that deterioration of the Peri-seals enables the piccolo tubes to vibrate, resulting in a broken piccolo tube. In this case, the location of the failure was more outboard than previous occurrences. This condition, if not corrected, may cause heat damage to the front spar that potentially affects the wing's load capability. Since an unsafe condition was identified, likely to exist or develop on an aircraft of this type design, CAA (Civil Aviation Authority) Netherlands issued AD NL-2006-011 to require inspection of the Piccolo Tubes and the surrounding structure to establish correct installation, as well as the replacement of the 460-series Peri-seals by the improved 600-series, which have a higher temperature limit.

Since the issuance of that AD, Fokker has developed a modification, published as Component Service Bulletin (CSB) D14000-57-007, for spare wing leading edge sections that may still contain the 460-series Peri-seals. For that reason, this EASA AD retains the requirements of AD NL-2006-011 and adds a limit for the allowed use of unmodified wing leading edge section as replacement part.

The corrective actions include inspection of the piccolo tubes and the wing leading edge for damage, and replacement of the Peri-seals, or repair of damage, as applicable.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 4,000 flight hours or 12 months after the effective date of this AD, whichever occurs first, do the actions in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-30-028, Revision 1, dated April 17, 2007.

(i) Inspect for damage of the piccolo tubes and the wing leading edge on the outside and on the inside at the access panels. If any damage is found that is beyond the limits specified in the service bulletin, repair before further flight.

(ii) Replace the 460-series Peri-seals in the riblets with improved 600-series Peri-seals.

(2) As of 12 months after the effective date of this AD, no person may install on any airplane a spare wing leading edge section unless the leading edge section has been modified in accordance with Fokker Component Service Bulletin D14000-57-007, dated April 17, 2007.

(3) Actions done before the effective date of this AD in accordance with Fokker Service Bulletin SBF100-30-028, dated May 18, 2006, are considered acceptable for compliance with the actions required by paragraph (f)(1) of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to European Aviation Safety Agency (EASA) Airworthiness Directive 2007-0229, dated August 15, 2007; Fokker Service Bulletin SBF100-30-028, Revision 1, dated April 17, 2007; and Fokker Component Service Bulletin D14000-57-007, dated April 17, 2007; for related information.

Material Incorporated by Reference

(i) You must use Fokker Service Bulletin SBF100-30-028, Revision 1, dated April 17, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8256 Filed 4-18-08; 8:45 am]



2008-08-19 Gulfstream Aerospace LP (Formerly Israel Aircraft Industries, Ltd.): Amendment 39-15473. Docket No. FAA-2008-0120; Directorate Identifier 2007-NM-327-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Gulfstream Model Gulfstream G150 airplanes, certificated in any category, serial numbers 201 through 239 inclusive.

Subject

- (d) Air Transport Association (ATA) of America Code 24: Electrical power.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Possible chafing between [the] electrical feeder cable connected to contactor 123P/2 and ground point 803GND, installed within the left DC power box, discovered during routine receiving inspection. This condition may exist on boxes installed on in-service aircraft. If this chafing condition is left unattended, an electrical short may develop, leading to disconnection of the battery and battery bus from the electrical system of the aircraft, [which could result in] overheating, arcing, smoke and fire.

The corrective action includes inspecting for chafing and arcing damage of the feeder cable, terminal lug and ground point, contacting Gulfstream for repair if any damage is found and repairing, installing new heat-shrink tubing if the tubing is missing or damaged, and repositioning the feeder cable.

Actions and Compliance

- (f) Unless already done, do the following actions. Within 50 flight hours or 30 days after the effective date of this AD, whichever occurs first, inspect the feeder cable, terminal lug 123P/2, and ground point 803GND for chafing and arcing damage, reposition the feeder cable to maintain an adequate gap, and do all applicable corrective actions. Do the actions in accordance with Gulfstream Alert Service Bulletin 150-24A-046, dated October 31, 2007. Do all applicable corrective actions before further flight.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Mike Borfitz, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2677; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Israeli Airworthiness Directive 24-07-10-11, dated October 31, 2007; and Gulfstream Alert Service Bulletin 150-24A-046, dated October 31, 2007; for related information.

Material Incorporated by Reference

(i) You must use Gulfstream Alert Service Bulletin 150-24A-046, dated October 31, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D-25, Savannah, Georgia 31402-2206.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8258 Filed 4-18-08; 8:45 am]



2008-08-20 Dassault Aviation: Amendment 39-15474. Docket No. FAA-2008-0116; Directorate Identifier 2007-NM-257-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Dassault Model Falcon 2000 airplanes, certificated in any category; all serial numbers; equipped with wing anti-ice telescopic tubes having part number (P/N) 5035-400 or 5035-500.

Subject

- (d) Air Transport Association (ATA) of America Code 30: Ice and rain protection.

Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

Wing anti ice telescopic tubes (P/N [part number] 5035-400 and 5035-500) ball joints were originally designed with high temperature polymer (KynelTM) sealing rings. Temperature induced cracking of these rings associated with long term wear has been encountered in a small number of cases. This degradation may lead to binding of the ball joint and high swiveling forces which may result in improper operation of the leading edge slats and also in failure of the ball joint mounting bracket with possible friction on the aileron control rod, which could lead, if combined with a failure of the aileron emergency actuator, to an aileron jamming.

A replacement carbon based material has been defined by the telescopic tube manufacturer Zodiac and can be applied per Zodiac Service Bulletins (SB) 5035-30-001 and 5035-30-002, resulting in P/N redesignations 5035-600 Amdt.A and 5035-700 Amdt.A, respectively.

The purpose of this Airworthiness Directive (AD), by requiring modification of the wing anti-ice telescopic tubes in accordance with the Zodiac service bulletins, is to ensure that no old definition sealing rings remain in operation beyond a life limit of 2,400 flight hours (FH) or 2,000 flight cycles (FC).

The unsafe condition is a jammed aileron, which results in reduced controllability of the airplane.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) At the later of the compliance times specified in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD, remove and modify the affected tubes in accordance with instructions contained in Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002.

(i) Before the telescopic tubes, P/N 5035-400 and 5035-500, exceed the limit of 2,400 flight hours, or 2,000 flight cycles, time-in-service since new, whichever occurs first.

(ii) At the earlier of the times specified in paragraphs (f)(1)(ii)(A) and (f)(1)(ii)(B) of this AD.

(A) Within 330 flight hours after the effective date of this AD.

(B) Within 7 months after the effective date of this AD.

(2) As of 7 months after the effective date of this AD, no person may install an affected telescopic tube P/N 5035-400 or 5035-500 in any aircraft as a replacement part, unless it has been modified in accordance with instructions contained in Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2006-0276, dated September 6, 2006; and Zodiac Service Bulletins 5035-30-001 and 5035-30-002, both dated April 15, 2002; for related information.

Material Incorporated by Reference

(i) You must use Zodiac Service Bulletin 5035-30-001, dated April 15, 2002; and Zodiac Service Bulletin 5035-30-002, dated April 15, 2002; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8253 Filed 4-18-08; 8:45 am]



2008-08-22 Boeing: Amendment 39-15476. Docket No. FAA-2007-29116; Directorate Identifier 2007-NM-064-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 737-30-1056, Revision 1, dated October 25, 2007.

Unsafe Condition

(d) This AD results from a report of charred insulation blankets and burned wires around the forward gray water composite drain mast found during an inspection of the forward cargo compartment on a Model 767-300F airplane. We are issuing this AD to prevent a fire near a composite drain mast and possible disruption of the electrical power system caused by a lightning strike on a composite drain mast, which could result in the loss of several functions essential for safe flight.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection To Determine Material of Gray Water Drain Masts

(f) Within 60 months after the effective date of this AD, inspect the forward and aft gray water drain masts to determine whether the drain masts are made of aluminum or composite. A review of airplane maintenance records is acceptable in lieu of this inspection if the material of the forward and aft gray water drain masts can be conclusively determined from that review.

(1) For any aluminum gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, no further action is required by this paragraph for that drain mast only.

(2) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, do the actions specified in paragraph (g) of this AD.

Installation of Bonding Jumper

(g) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD: Within 60 months after the effective date of this AD, install a bonding jumper between a ground and the clamp on the tube of the gray water composite drain mast, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-30-1056, Revision 1, dated October 25, 2007.

Actions Done Previously Using Previous Service Information

(h) Actions done before the effective date of this AD according to Boeing Special Attention Service Bulletin 737-30-1056, dated February 28, 2007, are considered acceptable for compliance with the corresponding actions specified in this AD provided the results of the resistance measurements meet the acceptable values specified in Boeing Special Attention Service Bulletin 737-30-1056, Revision 1, dated October 25, 2007.

Parts Installation

(i) As of the effective date of this AD, no person may install, on any airplane, a composite gray water drain mast, unless a bonding jumper is also installed, as specified in paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(k) You must use Boeing Special Attention Service Bulletin 737-30-1056, Revision 1, dated October 25, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 7, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8254 Filed 4-18-08; 8:45 am]



2008-08-23 Boeing: Amendment 39-15477. Docket No. FAA-2007-29029; Directorate Identifier 2007-NM-175-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

(b) Accomplishing the actions required by paragraph (g) and the initial inspections required by paragraph (h) of this AD ends the requirements of AD 98-11-04 R1, amendment 39-10984, for Model 737-200C series airplanes only. Operators of Model 737-100 and -200 series airplanes must continue to do the actions required by AD 98-11-04 R1.

Applicability

- (c) This AD applies to all Boeing Model 737-200C series airplanes, certificated in any category.

Unsafe Condition

(d) This AD results from a report of incidents involving fatigue cracking in transport category airplanes that are approaching or have exceeded their design service objective. We are issuing this AD to maintain the continued structural integrity of the entire fleet of Model 737-200C series airplanes.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Information

(f) The term "Revision E," as used in this AD, means Boeing Document D6-37089, "Supplemental Structural Inspection Document for Model 737-100/200/200C Airplanes," Revision E, dated May 2007.

Revision of the FAA-Approved Maintenance Inspection Program

(g) At the applicable time specified in Table 1 of this AD, incorporate a revision into the FAA-approved maintenance inspection program that provides no less than the required damage tolerance rating (DTR) for each structural significant item (SSI) listed in Revision E. (The required DTR value for each SSI is listed in Revision E.) The revision to the maintenance inspection program must include and must be implemented in accordance with the procedures in Section 5.0, "Damage Tolerance Rating (DTR) System Application," and Section 6.0, "SSI Discrepancy Reporting" of Revision E. Under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 et seq.),

the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

Table 1 – Compliance time for revising maintenance inspection program

For airplanes with SSIs –	Compliance Time
(1) Affected by the cargo configuration	Before the accumulation of 46,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later
(2) Not affected by the cargo configuration	Before the accumulation of 66,000 total flight cycles, or within 12 months after the effective date of this AD, whichever occurs later.

Initial and Repetitive Inspections

(h) Except as provided by paragraph (i) of this AD: At the applicable time specified in Table 2 of this AD, do the applicable initial inspections to detect cracks of all SSIs, in accordance with Revision E. Repeat the applicable inspections thereafter at the intervals specified in Section 3.0, "Implementation" of Revision E.

Table 2 – Compliance time for initial inspections

For airplanes with SSIs –	Compliance Time
(1) Affected by the cargo configuration	Before the accumulation of 46,000 total flight cycles, or within 4,000 flight cycles measured from 12 months after the effective date of this AD, whichever occurs later
(2) Not affected by the cargo configuration	Before the accumulation of 66,000 total flight cycles, or within 4,000 flight cycles measured from 12 months after the effective date of this AD, whichever occurs later.

(i) For any SSI that has been repaired or altered before the effective date of this AD such that the repair or design change affects your ability to accomplish the actions required by paragraph (h) of this AD: You must request FAA approval of an alternative method of compliance (AMOC) in accordance with section 39.17 of the Federal Aviation Regulations (14 CFR 39.17), at the initial compliance time specified in paragraph (h) of the AD; or do the actions specified in paragraphs (i)(1) and (i)(2) of this AD, at the times specified in those paragraphs, as an approved means of compliance with the requirements of paragraph (h) of this AD.

(1) At the initial compliance time specified in paragraph (h) of the AD, identify each repair or design change to that SSI.

(2) Within 12 months after the identification of a repair or design change required by paragraph (i)(1) of this AD, assess the damage tolerance characteristics of each SSI affected by each repair or design change to determine the effectiveness of the applicable SSID inspection for that SSI and if not effective, incorporate a revision into the FAA-approved maintenance inspection program to include a damage-tolerance based alternative inspection program for each affected SSI. Thereafter, inspect the affected structure in accordance with the alternative inspection program. The inspection method and compliance times (i.e., threshold and repeat intervals) of the alternative inspection program must be approved in accordance with the procedures specified in paragraph (l) of this AD.

Repair

(j) If any cracked structure is found during any inspection required by paragraph (h) or (i) of this AD, before further flight, repair the cracked structure using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

Inspection Program for Transferred Airplanes

(k) Before any airplane that is subject to this AD and that has exceeded the applicable compliance times specified in paragraph (h) of this AD can be added to an air carrier's operations specifications, a program for the accomplishment of the inspections required by this AD must be established in accordance with paragraph (k)(1) or (k)(2) of this AD, as applicable.

(1) For airplanes that have been inspected in accordance with this AD: The inspection of each SSI must be done by the new operator in accordance with the previous operator's schedule and inspection method, or the new operator's schedule and inspection method, at whichever time would result in the earlier accomplishment for that SSI inspection. The compliance time for accomplishment of this inspection must be measured from the last inspection accomplished by the previous operator. After each inspection has been done once, each subsequent inspection must be performed in accordance with the new operator's schedule and inspection method.

(2) For airplanes that have not been inspected in accordance with this AD: The inspection of each SSI required by this AD must be done either before adding the airplane to the air carrier's operations specification, or in accordance with a schedule and an inspection method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. After each inspection has been done once, each subsequent inspection must be done in accordance with the new operator's schedule.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle ACO has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair approval must specifically refer to this AD.

Material Incorporated by Reference

(m) You must use Boeing Document D6-37089, "Supplemental Structural Inspection Document for Model 737-100/200/200C Airplanes," Revision E, dated May 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The document contains the following errors:

(i) Pages 2.0.3 and 2.0.4, Revision D, of Section 2.0 and pages F-14.5, Revision D, and F-14.6, Revision Blank, of Section 8.2 exist; but are not specified in the List of Effective Pages.

(ii) Pages 7.0.43 through 7.0.46 inclusive of Section 7.0 and pages W.34.1 and W.34.2 of Section 11.1, as specified in the List of Effective Pages, do not exist.

(iii) The List of Effective Pages specifies incorrect revision levels for certain pages; the revision levels specified on each page are correct.

(iv) None of the pages are dated. The issue date for each revision is specified in the Revision Highlights section.

(2) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(4) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8320 Filed 4-18-08; 8:45 am]



2008-08-24 Boeing: Amendment 39-15478. Docket No. FAA-2007-0049; Directorate Identifier 2007-NM-168-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Boeing Model 737-600, -700, -700C, -800, and -900 series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 737-54-1043, dated May 2, 2007.

Unsafe Condition

- (d) This AD results from reports of failure of the drain tube assembly and support clamp on the aft fairing of an engine strut. We are issuing this AD to prevent failure of the drain tube assemblies and clamps on the aft fairings of the engine struts. Such a failure could allow leaked flammable fluids in the drain systems to discharge on to the heat shields of the aft fairings of the engine struts, which could result in an undetected and uncontrollable fire.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Replacement

- (f) Within 60 months after the effective date of this AD, replace the drain tube assemblies and support clamps on the aft fairing of the struts of engine number 1 and engine number 2 with new drain tube assemblies and clamps, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-54-1043, dated May 2, 2007.

Alternative Methods of Compliance (AMOCs)

- (g)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

- (2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Boeing Special Attention Service Bulletin 737-54-1043, dated May 2, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 8, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8328 Filed 4-18-08; 8:45 am]



2008-08-25 Boeing: Amendment 39-15479. Docket No. FAA-2006-26726; Directorate Identifier 2006-NM-205-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 747-400F airplanes as identified in Boeing Alert Service Bulletin 747-25A3370, Revision 1, dated April 27, 2006; and Model 747-400 series airplanes as identified in Boeing Alert Service Bulletin 747-25A3526, dated November 13, 2007; certificated in any category.

Unsafe Condition

(d) This AD results from a report that water from the dripshield entered the card file and damaged a circuit card, causing the AFT CARGO FIRE MSG message to be illuminated and resulting in an air turn back. We are issuing this AD to prevent water from entering the card file and damaging a circuit card. Failure of one or more of the 15 fuel system circuit cards in the card file could cause loss of fuel management, which could cause unavailability of fuel. Failure of one or more of the 35 fire detection circuit cards could cause a false message of a fire, or no message of a fire when there is a fire.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation

(f) Within 24 months after the effective date of this AD, install two drains and drain tubes in the dripshield above the M826 Card File over the nose wheel left side in the main equipment center at station 400, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3370, Revision 1, dated April 27, 2006 (for Model 747-400F series airplanes); or Boeing Alert Service Bulletin 747-25A3526, dated November 13, 2007 (for Model 747-400 series airplanes).

Installation According to Previous Issue of Service Bulletin

(g) Installing the drains and drain tubes is also acceptable for compliance with the requirements of paragraph (f) of this AD if done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 747-25A3370, dated September 8, 2005.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(i) You must use Boeing Alert Service Bulletin 747-25A3370, Revision 1, dated April 27, 2006; or Boeing Alert Service Bulletin 747-25A3526, dated November 13, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 7, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8327 Filed 4-18-08; 8:45 am]



2008-08-26 Boeing: Amendment 39-15480. Docket No. FAA-2007-29063; Directorate Identifier 2007-NM-049-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 767-30-0047, dated January 25, 2007; and Boeing Special Attention Service Bulletin 767-30-0048, dated January 25, 2007.

Unsafe Condition

(d) This AD results from a report of charred insulation blankets and burned wires around the forward gray water composite drain mast found during an inspection of the forward cargo compartment. We are issuing this AD to prevent a fire near a composite drain mast and possible disruption of the electrical power system caused by a lightning strike on a composite drain mast, which could result in the loss of several functions essential for safe flight.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection To Determine Material of Gray Water Drain Mast

(f) Within 60 months after the effective date of this AD, inspect the forward and aft gray water drain masts to determine whether the drain mast is made of aluminum or composite. A review of airplane maintenance records is acceptable in lieu of this inspection if the material of the forward and aft gray water drain masts can be conclusively determined from that review.

(1) For any aluminum gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, no further action is required by this AD for that drain mast only.

(2) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD, do the actions specified in paragraph (g) of this AD.

Installation of New Ground Bracket and Bonding Jumper

(g) For any composite gray water drain mast identified during the inspection or records check required by paragraph (f) of this AD: Within 60 months after the effective date of this AD, install a bonding jumper between the new ground bracket and the clamp on the tube of the gray water composite drain mast, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-30-0047, dated January 25, 2007 (for Model 767-200, -300, and -300F series airplanes); and Boeing Special Attention Service Bulletin 767-30-0048, dated January 25, 2007 (for Model 767-400ER series airplanes).

Parts Installation

(h) As of the effective date of this AD, no person may install, on any airplane, a composite gray water drain mast, unless a new ground bracket and bonding jumper are also installed, as specified in paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(j) You must use Boeing Special Attention Service Bulletin 767-30-0047, dated January 25, 2007; or Boeing Special Attention Service Bulletin 767-30-0048, dated January 25, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 7, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8317 Filed 4-18-08; 8:45 am]



2008-09-04 McDonnell Douglas: Amendment 39-15484. Docket No. FAA-2008-0031; Directorate Identifier 2007-NM-313-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to all McDonnell Douglas Model DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, and DC-8-43 airplanes; Model DC-8-51, DC-8-52, DC-8-53, and DC-8-55 airplanes; Model DC-8F-54 and DC-8F-55 airplanes; Model DC-8-61, DC-8-62, and DC-8-63 airplanes; Model DC-8-61F, DC-8-62F, and DC-8-63F airplanes; Model DC-8-71, DC-8-72, and DC-8-73 airplanes; and Model DC-8-71F, DC-8-72F, and DC-8-73F airplanes; certificated in any category.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance (AMOC) in accordance with paragraph (i) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Unsafe Condition

(d) This AD results from a design review of the fuel tank systems. We are issuing this AD to prevent the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Compliance

- (e) Comply with this AD within the compliance times specified, unless already done.

Revise the FAA-Approved Maintenance Program

(f) Before December 16, 2008, revise the FAA-approved maintenance program to incorporate the information specified in Appendixes B, C, and D of the Boeing DC-8 Special Compliance Item

Report, MDC-02K9030, Revision A, dated August 8, 2006. Accomplishing the revision in accordance with a later revision of the Boeing DC-8 Special Compliance Item Report, MDC-02K9030, is an acceptable method of compliance if the revision is approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA.

No Reporting Requirement

(g) Although the Boeing DC-8 Special Compliance Item Report, MDC-02K9030, Revision A, dated August 8, 2006, specifies to submit certain information to the manufacturer, this AD does not require that action.

No Alternative Inspections, Inspection Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

(h) After accomplishing the applicable actions specified in paragraph (f) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used unless the inspections, intervals, or CDCCLs are part of a later revision of Boeing DC-8 Special Compliance Item Report, MDC-02K9030, Revision A, dated August 8, 2006, that is approved by the Manager, Los Angeles ACO; or unless the inspections, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (i) of this AD.

AMOCs

(i)(1) The Manager, Los Angeles ACO, FAA, ATTN: Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(j) You must use Boeing DC-8 Special Compliance Item Report, MDC-02K9030, Revision A, dated August 8, 2006, to do the actions required by this AD, unless the AD specifies otherwise. (The revision date for this document is identified only on the title page and in the "Index of Page Changes" section of the document.) This document contains the following effective pages:

Pages	Revision	Date
Index of Page Changes Pages i through iii	A	August 8, 2006.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National

Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 4, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8532 Filed 4-21-08; 8:45 am]



2008-09-05 Boeing: Amendment 39-15486. Docket No. FAA-2007-29065; Directorate Identifier 2007-NM-142-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 27, 2008.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747SR, and 747SP series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 747-32A2482, dated June 14, 2007.

Unsafe Condition

(d) This AD results from a report of a fractured trunnion fork assembly. We are issuing this AD to prevent a fractured trunnion fork assembly, which could result in the collapse of a wing landing gear on the ground and possible damage to hydraulic equipment and the aileron and spoiler cables. Such damage could result in reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Bulletin

(f) The term "service bulletin," as used in this AD, means Boeing Alert Service Bulletin 747-32A2482, dated June 14, 2007.

Initial Inspection for Part Number, Serial Number, and Category

(g) Within 18 months after the effective date of this AD, inspect the pad-up area on the forward upper inboard surface of the trunnion fork assembly of both the left and right wing landing gears to determine the part number and serial number and to determine the category of the trunnion fork assemblies. A review of airplane maintenance or delivery records is acceptable instead of the inspection if the part number and serial number of the installed fork assembly can be conclusively determined from that review. Do the actions in accordance with the Accomplishment Instructions of the service bulletin.

Follow-On Actions for Category A, B, C, or D Trunnion Fork Assemblies

(h) If any part number and serial number identified as Category A, B, C, or D in Tables 2 and 3 of paragraph 1.E., "Compliance," of the service bulletin is found installed during the inspection required by paragraph (g) of this AD: At the applicable compliance time(s) listed in Table 4 or 5 of paragraph 1.E., "Compliance," of the service bulletin, except as provided by paragraph (i) of this AD, do the applicable action(s) in Table 1 of this AD and applicable related investigative/corrective actions, in accordance with the Accomplishment Instructions of the service bulletin.

Table 1.—Requirements for Category A, B, C, or D Trunnion Fork Assemblies

For –	Do –	And –	Or –
(1) Categories A and C trunnion fork assemblies	A detailed inspection for damage to the protective finish and for corrosion of the trunnion fork assembly and a high frequency eddy current (HFEC) inspection to detect cracks (Part 2)	An ultrasonic inspection to determine the wall thickness in the area forward of the outer cylinder attach lugs in 8 zones, and a hardness measurement if applicable (Part 3)	Do the terminating action (Part 5)
(2) Categories B and D trunnion fork assemblies	An ultrasonic inspection to determine the wall thickness in the area forward of the outer cylinder attach lugs in 8 zones, and a hardness measurement (Part 3)	None	None

(i) Where paragraph 1.E., "Compliance," of the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

Terminating Action

(j) Replacing the trunnion fork assembly of the wing landing gear with a trunnion fork assembly identified in Part 5 of the Accomplishment Instructions of the service bulletin, in accordance with and at the applicable time specified in Table 4 or 5 of paragraph 1.E., "Compliance," of the service bulletin, constitutes terminating action for the requirements of this AD for that side only.

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(1) You must use Boeing Alert Service Bulletin 747-32A2482, dated June 14, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 14, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8530 Filed 4-21-08; 8:45 am]



2008-09-07 Boeing: Amendment 39-15488. Docket No. FAA-2008-0411; Directorate Identifier 2008-NM-061-AD.

Effective Date

- (a) This airworthiness directive (AD) is effective May 8, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to all Boeing Model 757-200, -200PF, -200CB, and -300 series airplanes, and Model 767-200, 767-300, and 767-300F series airplanes, certificated in any category.

Unsafe Condition

- (d) This AD was prompted by an error in the operating program software (OPS) of the engine indication and crew alerting system (EICAS). The error prevents the display of an advisory message to the flight crew of a left engine fuel filter contamination and imminent bypass condition, which may indicate an imminent multiple engine thrust loss or engine malfunction event due to fuel contamination. We are issuing this AD to prevent malfunction and thrust loss on both engines, which could result in a forced off-airport landing.

Compliance

- (e) Comply with this AD within the compliance times specified, unless already done.

Revision of Airplane Flight Manual (AFM)

- (f) Within 30 days after the effective date of this AD, revise the Limitations section of the applicable AFM to include the following. This may be done by inserting a copy of this AD into the AFM.

"If the STATUS cue shows while on the ground after engine start or during flight, select the status page on the secondary EICAS display, and verify the "L ENG FUEL FILT" message is not shown. If the "L ENG FUEL FILT" message is not shown on the status page, the secondary engine parameters may be reselected on the secondary EICAS display, or the display may be blanked. If the "L ENG FUEL FILT" message is shown on the status display, accomplish the ENGINE FUEL FILTER non-normal checklist as published in the Boeing Quick Reference Handbook. If on the ground, check the Dispatch Deviations Guide (DDG), or operator equivalent.

In the event that the status level "L ENG FUEL FILT" and advisory level "R ENG FUEL FILT" messages are simultaneously shown, an impending fuel filter bypass condition exists on both engines.

With both messages shown, airplane fuel system contamination may be present and may result in erratic engine operation or flameout.

Further flight crew action in response to either or both the "L ENG FUEL FILT" status-level message and the "R ENG FUEL FILT" advisory level messages being shown are not established by Boeing or the FAA. Any further flight crew action should be determined by individual operator policy.

Boeing policy on flight crew use of status-level messages has not changed. After engine start, any condition having an adverse effect on safe continuation of the flight appears as an EICAS alert message (Warning, Caution, or Advisory). If other status-level messages are shown as a consequence of complying with these temporary operating instructions, the flight crew should respond in accordance with the appropriate operator policy.

Dispatch of the airplane with an inoperative EICAS display unit is prohibited.

(g) If all affected airplanes in an operator's fleet have been verified by the operator to have EICAS computer part number S242N701-1001 and only EICAS OPS versions other than Version 6 software that are FAA approved for that airplane, then accomplishment of the actions specified in paragraph (f) of this AD is not required.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Judy Coyle, Aerospace Engineer, Propulsion Branch, ANM-140S, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6497; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(i) None.

Issued in Renton, Washington, on April 14, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-8653 Filed 4-22-08; 8:45 am]